## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	Т	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE	1_	
OPERATOR		

CONDITIONS OF APPROVAL, IF ANYE

## JIL CONSERVATION DIVISIC IL P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Forn	C-1	03	
Revis	ed	10-	1-7

5a. Indicate Type of Lease

State

DERATOR DESCRIPTION	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  [DO NOT USE THIS FORM FOR POPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIS  USE "IMPRICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL X GAS DEFICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)	J. Unit Agreement Name Eunice Monument South Unit
Name of Operator	8. Farm or Lease Name
Chevron U.S.A. Inc.	9. Well No.
Address of Operator  D. O. Boy 670 Hobbs NM 98240	346
P.O. Box 670 Hobbs, NM 88240	10. Field and Pool, or Wildcat
P 560 FEET FROM THE East LINE AND 659	Eunice Monument G/SA
South LINE, SECTION 10 TOWNSHIP 21 S RANGE 36E	RMPM.
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3582' GL	Lea
Check Appropriate Box To Indicate Nature of Notice, Repo	ort or Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  PLUG AND ABANDON  REMEDIAL WORK  COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JO  OTHER COMPletic	ALTERING CASING PLUG AND ABANDONMENT
OTHER	
Cleanout from 3947 to 3970 and displace hole w/ 8.6 CKF at 3880-84, 3906-16, 3930-54. Acidize w/2800 gallons 15 prepare to perf zone 1,2,&3 w/4" guns 180° phased at 376 3842-66 w/ 1 JHPF. Acdz w/5100 gallons 15% NEFE HCL, sto 2 3/8. GIH w/production tubing. NU Injection head,	5% NEFE HCL. Swab 58-74, 3784-3804, 3814-32, wab, change rams f/2 7/8 test casing to 600psi,
ok. Turn over to production. Work performed August 19	through 25, 1507.
	•
	•
	•
16. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
m. E. ahm Tire Staff Drilling Engin	eer August 24, 1987
ORIGINAL SIGNED BY JERRY SEXTON	AUG 2 6 1987
DISTRICT I SUPERVISOR	DATE