

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 29991
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. VA 606-1
7. Lease Name or Unit Agreement Name Grama Ridge 35 State
8. Well No. 1
9. Pool name or Wildcat WILDCAT

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole
2. Name of Operator SOUTHWEST ROYALTIES, INC.
3. Address of Operator P.O. BOX 11390; MIDLAND, TX
4. Well Location Unit Letter I : 2310 Feet From The South Line and 990 Feet From The East Line Section 35 Township 21S Range 33E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3666' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Shot 10740

Shot 9015 8500'
8486

11/25/12

Propose to circulate hole w/9 ppg mud to fill hole & POOH w/2 3/8" tbg. Set 5 1/2" CIBP @ 12,000' & dump 35' of cmt on top. Cut off 5 1/2" csg @ ±10,900' & POOH w/csg. Spot 190' cmt plug (36 sx) @ 9000'. Tag plug. Spot 160' cmt plug (55 sx) across 7 5/8" csg cut @ 5794'. Tag plug. Spot 150' plug (62 sx) across 10 3/4" shoe @ 5183'. Tag plug. Spot 140' plug (58 sx) @ 3850'. Tag plug. Spot 110' plug (46 sx) across 13 3/8" shoe @ 670'. Tag plug. Cut off csg & spot 10 sx surf plug. Weld on cap and erect P&A marker.

Added plug
2400-2540

915-6341301

RT not added =
w/o prod rpt.
any? before
add pool
DS

ft. 8100
7000 0.00

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James Blount TITLE Area Supervisor DATE 9-11-97
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)
ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

OCT - 8 1997

SOUTHWEST ROYALTIES

BRIGHT GRAMA RIDGE 35 3741

PAGE
OF

DT 588

OF

DATE 6-26-44

PROPOSED

10 54 SURF PLUG

46 62 555-665'

58 52 2400'-2540'

58 52 3710-3850'

62 12 5090-5240'

58 52 5690-5850'

36 12 8810-9000'

100 8 12 115' 1100'

PSTD 13,150'

13 3/4" @ 615'

TOP Salt ~~to~~ per Chas
Wellman

OK

Excepted to 111-P
well was originally
done & complete
before brought into
the Potash one
in 1988.

10 3/4" 40.5# @ 5123'

7 1/2" CAT OFF @ 5774'

2 3/4" N-80 @ ± 12,600'

TOP @ 19935'

11" 10 1 5 11 11 12 074'
1 3/4" 55.94 GR 42 @ 12,778'

ZONE OF INTEREST: 12,614-72'