

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
1625 N. French
Hobbs, NM 88240

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

ELLIOTT OIL COMPANY

3a. Address

P.O. Box 1355 Roswell, NM 88202

3b. Phone No. (include area code)

505-622-5840

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

4195' FNL, 2310' FWL of Sec. 1, T21S, R37E (N)
Lea County, NM

5. Lease Serial No.

LC-065525

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement Name and/or No.

<25248>
COOGAN FEDERAL

8. Well Name and No.

2

9. API Well No.

30-025-30469

10. Field and Pool, or Exploratory Area
Drinkard

11. County or Parish, State

Lea, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. Set CIBP at 6760'. - *ZA Drinkard*
 2. Perforate Blinbry pay at 5940' - 54', 5960' - 66', 5990' - 6000' (4spf).
 3. Acidize new perforations w/ 1500 gals. 15% HCl-NE-FE w/ 60 balls.
 4. Frac entire Blinbry zone w/ 100,000# cross link gel frac.
 5. Put well on production.
- Estimated starting dat 7/15/00, estimated duration 4 days.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Stephen L. Elliott

Title Managing Agent

Signature

Date 6/19/00

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

(OPIG. SGD.) DAVID R. GLASS

PETROLEUM ENGINEER

Date

JUN 23 2000

s not warrant or
he subject lease

Office

**Well Completion Or Recompletion Report
And Log (Form 3160-4) Required After The
Well Has Been Completed To The Blinbry.**

time for any person knowingly and willfully to make to any department or agency of the United
ny matter within its jurisdiction.

RECEIVED
2000 JUN 20 A 8:08

RECEIVED
JUN 22 1956

JUN 22 1956

RECEIVED

