

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-39

DISTRICT OFFICE
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT OFFICE
P.O. Drawer DD, Aztec, NM 88210

DISTRICT OFFICE
1000 Rio Grande Rd., Aztec, NM 87410

WELL API NO.
30-025-30512
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name Eunice Monument South Unit
2. Name of Operator Chevron U.S.A. Inc.	8. Well No. 643
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Foot name or Wildcat Eunice Monument GB/SA
4. Well Location Unit Letter <u>X</u> : <u>1275</u> Feet From The <u>South</u> Line and <u>1275</u> Feet From The <u>East</u> Line Section <u>6</u> Township <u>21S</u> Range <u>36E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3577

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
FILL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOBS ☐
	OTHER Completion ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed: 6-14-89 thru 6-25-89

POH w/rods. Tag 3990', spot 5sx 12/20 sd (3990-3995'), set pkr at 3848', est IR, TIH w/ CICR to 3848'. Squeeze zone 3 (3898-3948) w/200sx C1 C. Perf zones 2,3 &4 w/4" premium, 180°, 2 SPF, 140 holes, 3848-52, 3854-56, 3960-64, 3870-72, 3881-85, 3898-3902, 3906-26, 3968-82, 4002-06, 4010-22. Acidize perfs 4002-4022 w/500 gallons 15% NEFE. Acidize perfs 3968-3982 w/350 gallons, acdz perfs 3898-3926 w/700 gallons 15% NEFE. Swab test. Straddle acdz perfs 4002-4022 w/900 gallons & 250# blk. & perfs 3968-82 w/900 gallons & 200# blk and perfs 3898-3926 w/1600 gallons and 400# blk. Swab test perfs 3898-4022. Acdz perfs 3848-3885 w/900 gallons 15% NEFE. Swb test. Re-acdz perfs 3848-3885 w/1600 gallons gelled 15% NEFE HCL. Reset RBP at 3892, pkr at 3793. Acidize 3845-3885 w/1200 gallons 15% NEFE HCL. Swab. TIH w/prod. tbg to 3974, SN 3939. Run production equip. Turn over to production dept.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. L. Elmore TITLE Technical Assistant DATE 7-3-89

TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

Eddie W. Seay

JUL 06 1989

APPROVED BY Oil & Gas Inspector TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30512
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Eunice Monument South Unit
8. Well No. 643
9. Pool name or Wildcat Eunice Monument GB/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Chevron U.S.A. Inc.	
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	
4. Well Location Unit Letter <u>X</u> : <u>1275</u> Feet From The <u>South</u> Line and <u>1275</u> Feet From The <u>East</u> Line Section <u>6</u> Township <u>21S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3577'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed: 5-17-89 thru 5-18-89 TD: 4050 PB: 3990

POH w/pump and rods. Run GR/CCL/CET 3990-3500'. Set RBP at 3985', pkr at 3954'. Swab zone 4 perfs. Reset RBP at 3954' and pkr at 3879'. Swab zone 3 perfs. Reset RBP at 3985'. Pkr at 3954'. Pump red dye down BS. Swab zone 4 perfs. Rec. red water. TIH w/production tbg to 3974'. Run pump and rods. Hang on. Test pump action, ok. RDMOPU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. K. Elmore TITLE Technical Assistant DATE 5-19-89

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAY 25 1989

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30512
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator

P.O. Box 670, Hobbs, NM 88240

4. Well Location

Unit Letter X : 1275 Feet From The South Line and 1275 Feet From The East Line

Section 6 Township 21S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3577

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed: 3-16- 3-21-89

POOH w/production equipment. Test casing to 500psi, ok. Set CICR at 3990'. Batch mix 50sx C1 C. Sqzd perfs f/4002' to 4022'. Displace w/FW. Left 19sx cmt above rtnr. Drld cmt f/3874' to 3990'. Displace hole w/CKF. Acidize w/3250 gallons 15% NEFE HCL. Flushed to bottom perf w/ CKF. Swab. RIH w/production tbg to 3972'. Run rods and pump. Test pmp equipment to 500psi, ok. Turn over to production.

Note* This well was originally afe'd to acidize only. The decision to sqz the well came while on the job.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry Sexton TITLE Technical Asst. DATE 3-27-89

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAR 29 1989