Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

	ATION DIVISION	WELL API NO.
DISTRICT II Sonto En Mous L	P.O. Box 2088 TRICT II Drawer DD Artesia NM 88210 Santa Fe, New Mexico 87504-2088	
DISTRICT III	10,200 0,504-2000	30-025-30512 5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS O (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO D DIFFERENT RESERVOIR. USE "APPLICATION I (FORM C-101) FOR SUCH PROPOSAL	DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
I. Type of Weil: OIL GAS WELL WELL OTHER		Eunice Monument South Unit
2. Name of Operator		8. Well No.
Chevron U.S.A. Inc. 3. Address of Operator		643
P.O. Box 670, Hobbs, NM 88240		9. Pool name or Wildcat Eunice Monument GB/SA
Unit Letter X: 1275 Feet From The Sout	th Line and 127	5 Feet From The East Line
Section 6 Township 21S	Range 36E	<u> </u>
27777777777	whether DF, RKB, RT, GR, etc.)	NMPM Lea County
11. Check Appropriate Box to Ind	igate Marine of Marine D	<u> </u>
11. Check Appropriate Box to Ind. NOTICE OF INTENTION TO:		eport, or Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CASING	CASING TEST AND CE	
OTHER:	OTHER: completi	
12. Describe Proposed or Completed Operations (Clearly state all pertinent diwork) SEE RULE 1103.	1	
,		3 322
Work performed: 2-20-89 thru 2-	24-89 TD: 4050	PB: 4040
MIPU. TIH and tag TOC at 3954'. w/CBL/NCL/CCL/GR and CET. Spot Swab. RIH w/4" csg guns. Perfo at 180° phasing. RIH, set pkr a zone 3 3898-3902 (8 holes), 3906 (28 holes) 2 JHPF 4" guns, 180° w/925 gallons 15% NEFE HCL. Res gallons 15% NEFE HCL. Swab. TI Set TAC w/10K, RDMOPU. Turn ove	400 gallons 15% NEFE rated 4002-4006 and at 3597. Flush acid = -40 (68 holes) 3944-aphase, Set RBP at 3958 at RBP at 3958 at RBP at 3958 at W/ 2 7/8" j-55 tbg	HCL across 4020-3620'. 4010-4020. w/2JHPF to perfs. Swab. Perf 48 (8 holes), 3968-3982 92'. Acdz perfs 3968-82 dz perfs 3898-3948' w/2225 to 4031'. ND BOP, NUWH.
I hereoy certify that the information above is true and complete to the best of my knowle	adge and belief.	
ρ / C_{A}	mme_Technical_Asst	2.27.00
TYPE OR PRINT NAME	— ime <u>leconical</u> Assi	DATE 2-27-89
Orig. Signe 'tw		TELEPHONE NO.
(This space for State Use) Paul Kauf Geologist		MAR 1 1989
APPROVED BY	— mle ——————	MILLI T (AAA

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

(This space for State ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	T.	FEB 2 3 1989
TYPE OR PRINT NAME		TELEPHONE NO.
SKINATURE (L. Elmore) III	Technical As	DATE
I hereby certify that the information above is true and complete to the best of my knowledge and		2 21 00
work) SEE RULE 1103. 2-11-89 Drlg 7 7/8" hole. Drlg and survey Circulate for logs. Log w/ DLL/RXO/GR, #2 Ran 95 jts. 5 1/2", K-55, 15.5# to 4050'. lead and tail w/250sx Cl C. Displace w/FW. ND BOP's, cut off landing joint. Set slips spool. Pressure test to 2800psi, ok. Inst. 2400 hrs. 2/15/89.	to 4050'. TD 7 CNL/LDT/GR, #3 S FC at 3964'. Ce Bumped plug. w/50,000#. Ins	7/8" hole 2-14-89. onic/GR. Circulate. ment w/550sx C1 C Circ. 62sx cmt to surf. tall packoff and tbg
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, as		ing estimated date of starting any proposed
OTHER:	CASING TEST AND CE	MENT JOB (X.)
PULL OR ALTER CASING	COMMENCE DRILLING	
TEMPORARILY ABANDON CHANGE PLANS	REMEDIAL WORK	ALTERING CASING
Check Appropriate Box to Indicate NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON	SUB	SEQUENT REPORT OF:
11. Check Appropriate Box to Indicate	Manus Child	<u>\</u>
Section 6 Township 21S R. 10. Elevation (Show whether	nnge 36E 1 DF, RKB, RT, GR, etc.)	NMPM Lea County
Unit Letter X: 1275 Feet From The South	Line and 127	Teet Flour file
P.O. Box 670, Hobbs, NM 88240		Eunice Monument GB/SA
3. Address of Operator		9. Pool name or Wildcat
2. Name of Operator Chevron U.S.A. Inc.		8. Weil No.
1. Type of Weil: OIL WELL X WELL OTHER		Eunice Monument South Unit
SUNDRY NOTICES AND REPORTS ON WE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PE (FORM C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III	07202000	5. Indicate Type of Lease STATE X FEE
P.O. Box 2088 DISTRICT II Sonto Fo Nov. Marion 97504 2009		30-025-30512
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION		WELL API NO.
District Office		Revised 1.1-69

RECEIVED

FEB 22 1989

OCD MORRS OFFICE Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-39

District Office	Kevised 1-1-39
DISTRICTI P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVIS	ION WELL API NO.
P.O. Box 2088	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	30-025-30512 5. Indicate Type of Lease
DISTRICT III	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
	or search of at Cas Least 100
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC	KTOA 7
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	·
1. Type of Weil: OIL GAS WELL X WELL OTHER	
	Eunice Monument South Unit
2. Name of Operator	8. Weil No.
Chevron U.S.A. Inc. 3. Address of Operator	643
P.O. Box 670, Hobbs, NM 88240	9. Pool name or Wildcat
4. Well Location	Eunice Monument GB/SA
Unit Letter X: 1275 Feet From The South Line and	1275 Feet From The East Line
Unit Letter A: 12/3 Feet From The South Line and	1275 Feet From The East Line
Section 6 Township 21S Range 36E	NMPM Lea Court
Section Township 213 Range 30E	VATATE TAE
	······································
11. Check Appropriate Box to Indicate Nature of No.	Price Person and Other Person
MOTICE OF INTENTION TO:	_
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	OPK ALTERING CASING
	ORK ALTERING CASING
TEMPORARILY ABANDON L CHANGE PLANS COMMENCE	DRILLING OPNS. 🗵 PLUG AND ABANDONMENT 🔝
PULL OR ALTER CASING CASING TEST	T AND CEMENT JOB
OAOMA 123	AND CEMENT WB
OTHER: OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details)	ates, including estimated date of starting any proposed
work) SEE RULE 1103.	
Spud 12 1/4" hole 2-9-89. Drilling and surveying to	
Run 29 joints 8 5/8", 24#, K-55, ST&C, set at 1224'.	
Class C. Displace with BW. Circ. 200sx to surface.	Cut off and weld on wellhead.
Test void to 750psi, ok. WOC 23 hrs.	•
·	
	•
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIONATURE X E. Elmou TIME Techni	ical Assistant 2-21-89
TOTAL CO. TOTAL	
TYPE OR PRINT NAME	TELEPHONE NO.
(This space for State Lise)	
(This space for State Line) ORIGINAL SIGNED BY JERRY SEXTON	rrn 9 2 1000
DISTRICT I SUPERVISOR	FEB 2 3 1989
APPROVED BY	DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 22 1989

Property of the second

OCD HOBBS OFFICE