Form 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTE BURE, OF LAND MANAGEME		Expires Augus 3. LEASE DESIGNATION NM 61601 6. IF INDIAN. ALLOTTE	AND SERIAL NO
(Do not use thi	NDRY NOTICES AND REPORTS form for proposals to drill or to deepen or plu Use "APPLICATION FOR PERMIT_" for such	DN WELLS		
1. OIL GAS WELL WELL	7. UNIT AGREEMENT NAME			
2. NAME OF OPERATOR			8. FARM OR LEASE NAME	
Santa Fe	Bilbrey 22 Fed Com			
3. ADDRESS OF OPERATOR 500 W. Illinois, Suite 500, Midland, TX 79701			9. WBLL NO.	
4 LOCATION OF WELL (	10. FIELD AND POOL, OR WILDCAT			
See also space 17 be At surface	Und. Bilbrey Morrow			
	11. SEC., T., E., M., OE BLE. AND BURVET OF ARMA			
2310' FEL	and 660' FSL, Sec. 22, T-21S,	K-32E Unit O	Sec. 22, T-2	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR. etc.)			12. COUNTY OR PARISH	13. STATE
API # 30-025-3	0873 3710.7	7' GR	Lea	NM
16.	Check Appropriate Box To Indicate	Nature of Notice, Report, or O	ther Data	
NOTICE OF INTENTION TO: SUBSE			UENT REPORT OF :	
TEST WATER SHUT-( Practure treat Shoot or acidize Repair Well (Other)	DEFPULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANE	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) <u>Spud</u> and <u>se</u> (Note: Report results (Completion or Recouple	of multiple completion	ASING
	R COMPLETED OPERATIONS (Clearly state all pertin f well is directionally drilled, give subsurface lo	ent details and give pertinent dates.	including estimated dat	e of starting any

- 6-26-90: Spud 17<sup>1</sup><sub>2</sub>" hole at 5:00 p.m.
- 6-27-90: Depth 692'. RU and ran 16 jts 13-3/8" 48# H-40 casing and set at 692'. Cement w/ 50 sx thixotropic cmt followed by 5 BBL water spacer followed by 150 gal flo-check followed by 5 BBL spacer followed by 50 sx thixotropic followed by 5 BBL spacer then 150 gal flo-check then 5 BBL spacer then 500 sx Cl C w/ 4% gel followed by 250 sx Cl C w/ 2% CaCl<sub>2</sub>. Circulated 10-15 sx to pit. Plug down at 6:15 p.m. WOC.
- 6-28-90: WOC total of 6 hrs (Option II). Tested casing to 1000 psi okay. Install rotating head. Pick up BHA and trip in hole. Resume drilling operations.

ACCUSTED FOR FLOORD AR

DIRECT DECEMBER OF THE AMOUNT OF T

		D. FL. BAD, NEW MEXICO		
18. I hereby certify that the foregoing is true a SIGNED	nd correct <u> <u>     TITLE</u> Sr. Production Cler</u>	k July 2, 1990		
(This space for Federal or State office use)				
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	<b>TITLE</b>	DATE		

## \*See Instructions on Reverse Side

RECHINGED.

3

i

i

Т

JUL 1 1 1990 OCD MOBBS OFFICE