

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on
reverse side)

BLM Roswell District
Modified Form No.
ND60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

NM-14791

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

New Mexico Federal

9. WELL NO.

#5

10. FIELD AND POOL, OR WILDCAT

Hat Mesa Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 4-T21S- R32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Strata Production Company

3a. Area Code & Phone No.

(505) 622-1127

3. ADDRESS OF OPERATOR P. O. Box 1030

700 Petroleum Bldg., Roswell New Mexico 88202-1030

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

330' FNL & 860' FWL

14. PERMIT NO.

API 30-025-31146

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3646' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

5/19/92-RU Real Well Service rig. TOH w/tbg, rods and pump.

5/20/92-Perf (14) .42 holes as follows: 6796-6810' (1 spf). Acidize w/1400
7½% NeFe. Swab test.

5/22/92-Perf. (12) .42 holes as follows: 6605'-6611' (2 spf). Acidize w/1200
gal. 7½% NeFe. Frac via 2 7/8" tbg. w/25,000# 16/30 RC, 350 BBLs 35#
gelled 2% KCl.

5/28/92-TIH w/263 jts. 2 7/8" tbg. Set MA @ 8172', SN @ 8137', TA @ 5401'.
TIH w/2½"x2"X20' pump, (220) 3/4" rods, (104) 7/8" rods. Started
unit and release rig.

Well placed on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Carol J. Garcia

TITLE Production Supervisor

DATE

11/19/92

(This space for Federal or State office use)

APPROVED BY

David R. Hays

TITLE

DATE

12/30/92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side