

Submit 3 Copies  
to Appropriate

District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)
30-025-31409
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name EUNICE MONUMENT SOUTH UNIT
8. Well No. 639
9. Pool name or Wildcat EUNICE MONUMENT GB-SA

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	
4. Well Location Unit Letter <u>Q</u> : <u>1280</u> Feet From The <u>EAST</u> Line and <u>1330</u> Feet From The <u>SOUTH</u> Line Section <u>5</u> Township <u>21S</u> Range <u>36E</u> NMPM <u>LEA</u> County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3576 GE	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <u>SQZ, PERF, ACDZ</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including  
estimated date of starting any proposed work) SEE RULE 1103.

MIRU, POOH WITH PRODUCTION EQUIP.  
SET CICR AT 3713', PUMP 70 SXS. OF CEMENT INTO PERFS.  
DRILL OUT CICR, SET NEW CICR AT 3713' AND RESQUEEZE PERFS.  
DRILL OUT CICR. PERF AT 3842'-3791' WITH 4" GUNS,2 JHPF, 120 DEG. PHSD,45 HOLES.  
ACIDIZE PERS WITH 2000 GALS OF 15% NEFE, SWAB BACK ACID.  
RETURN TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECH. ASSISTANT DATE 5/4/92  
TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO (915)687-7812

APPROVED BY Paul Kautz TITLE Geologist DATE MAY 10 1992  
CONDITIONS OF APPROVAL, IF ANY: