

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) <b>30-025-31433</b>	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name <b>ARROWHEAD GRAYBURG UNIT</b>	
8. Well No. <b>125</b>	
9. Pool name or Wildcat <b>ARROWHEAD/GRAYBURG</b>	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		2. Name of Operator <b>CHEVRON U.S.A. INC.</b>	
3. Address of Operator <b>P.O. BOX 1150 MIDLAND, TX 79702 ATTN: WENDI KINGSTON</b>		4. Well Location Unit Letter <b>H</b> : <b>2075</b> Feet From The <b>NORTH</b> Line and Section <b>35</b> Township <b>21S</b> Range <b>36E</b> <b>660</b> Feet From The <b>EAST</b> Line County <b>LEA</b>	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) <b>3530' GL</b>			

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <b>SWAB, POLYMER TREAT</b> <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including  
estimated date of starting any proposed work) SEE RULE 1103.

MIRU. SWAB TEST PERFS 3844'-3819'.BLEND & PUMP UP TO 3000 BBBL'S  
OF 3500 TO 5000 PPM POLYMER SOLUTION. CIRC CLEAN.  
RIH W/TBG. RDMO.  
TURN WELL OVER TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		DATE: <b>10/16/95</b>	
SIGNATURE <i>Wendi Kingston</i>	TITLE <b>TECH. ASSISTANT</b>	TELEPHONE NO. <b>(915)687-7826</b>	
TYPE OR PRINT NAME <b>WENDI KINGSTON</b>			
APPROVED BY <i>Wendi Kingston</i>		DATE <b>OCT 19 1995</b>	
CONDITIONS OF APPROVAL, IF ANY:			

