

R.M. OIL CONS. CO. INC.
P.O. BOX 1980
MOBBS, NEW MEXICO 88444

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Collins & Ware, Inc.

3. Address and Telephone No.
303 W. Wall, Ste. 2200, Midland, TX 79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
O, 660' FSL & 1980' FEL, Sec. 18, T21S, R32E

5. Lease Designation and Serial No.

NM 14328

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Federal N.L. # 2

9. API Well No.

30-025-31518

10. Field and Pool, or Exploratory Area

Lost Tank Delaware

11. County or Parish, State

Lea NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other P & A
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PBTD 8424: 5 1/2" 17# Lt&C J55: 8482'. Perfs now open: 8267-8282; 7005-7019
8 5/8" csg. @ 4471: 13 3/8" @ 822'.

Set CIBP @ 8240 w/35' cement on top; set CIBP @ 6985 w/35' cement on top.
Displace hole w/9# + mud, 20-25 Vis. Set 50 sx. plug @ 4697-4245 across shoe 8 5/8"
Cut 5 1/2" csg. @ 3400'+-; POOH & lay down same. Run back tbg. to stub of 5 1/2"; spot
60 sx. plug @ 3626'-3174'. Spot 60 sx plug in 8 5/8" 925-719. Put 20 sx plug @ surf.
Install marker.

14. I hereby certify that the foregoing is true and correct

Signed Max Guerry Title Regulatory Mgr.

Date 8-30-93

(This space for Federal or State office use)

Approved by (ORIG. SEC. 106 C. 1 ARA)
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date 9/22/93

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side