Submit 3 Copies

to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office	OII	. CONSERVAT	TON DIVISION					
DISTRICTI			x 2088					
P.O. Box 1980, Hobbs, NM 88240		Santa Fe, N	lew Mexico 875	04-2088				
DISTRICT II								
P.O. Drawer Dd, Artesia, NM 8821	O .				30-025-32	ed by OCD on New Well	s)	
DISTRICT III					5. Indicate Ty			
1000 Rio Brazos Rd., Aztec, Nm 87	410				,,	STATE	X	FEE
					6. State Oil 8	Gas Lease No.	<del></del> -	
		_			N/A	C D31 F8928 MO'		
SUNDRY NOTICES AND REPORTS ON WELLS								
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"						or Unit Agreement Nam	<i>                                     </i>	
	(FORM C-101) FOR S		PERMIT"		ARNOTT-R	AMSAY (NCT-C	j	
1. Type of Well:	i same tell tell tell	OUT HO OSALS.						
OIL	GAS							
2. Name of Operator	WELL X	OTHER			1			
CHEVRON (	U.S.A. INC.				8. Well No.			
3. Address of Operator						1	7	_
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS						Wildcat		
4. Well Location Unit Letter	1	1920 -			EUMONT G	AS		
Section	21	1830 Feet From The	SOUTH 21 SOUTH	Line and	***	600 Feet From The	WES	ST Line
			how whether DF, RKB, RT, GR, etc	Range	36 EAST	NMPM	LEA	County
			3592' GL					
11	Check Appropriate Box	to Indecate Nature of No	tice, Report, or Other Data			<u> Xannadalanin</u>		
PERFORM REMEDIAL WORK	INTENTION TO:	_	SUBSEC	UENT REPOR	IT OF:			
TEMPORARILY ABANDON	PLUG AND ABANDON	<b>_</b>	REMEDIAL WORK			ALTER CASING		
PULL OR ALTER CASING	CHANGE PLANS		COMMENCE DRILLING OPNS.			PLUG AND ABAN		
OTHER:	L	<del></del>	CASING TEST AND CMT JOB					
			OTHER: DRILLING	SUMMARY				X
12. Describe Proposed or Completed	Operations(Clearly state all pertinent of	etails, and give pertinent date	includes					
esticated date of starting any prop	osed work) SEE RULE 1103.	gro per amont date	e, mainaid					
MIRH V 2.D	#1 IN 2 4 04 CDUD 40 4	48 1101 = 441 = -						
RIIN 9 E/O" (	#1 IN 3-4-94. SPUD 12 1/	4" HULE AND DRILI	. TO 1460', TD 12 1/4"	HOLE.				
WAIT ON CE	CASING TO 1460'. PUMP	650 SXS. CEMENT	AND CIRC. 60 SXS. TO	SURFACE.				
DRILL TO TO	MENT FOR 12.5 HRS. DR AT 3850' WITH A <i>7 7/</i> 8'	ILL OUT FLUAT AN	D SHOE.					
	CASING FROM SURFACE							
	XS. CEMENT.	10 3850.						
	LLHEAD AND RELEASE RI	C ON 2 12 04						
	THE NO HELEAGE N	u un 3-10-94.						
hereby certify that the information above	e is true and complete to the best of r	ny tono wledge and belief,						
SIGNITURE 77.7	Mathem		TECH. ASSISTANT	n	ATE:	3-17-94		
YPE OR PRINT NAME	D.D. MATTHEWS			<u>-</u>		3-17-84		
CONTINUE MANYE	P.R. MATTHEWS			TE	LEPHONE NO.	(915)687-795	0	
		Orig.	Signed by					<del></del> -
PPROVED BY ONDITIONS OF APPROVAL, IF ANY:		TITLE Pau	l Kautz	DA	TE	HÀN	. 394	†
		Ge	ologist		<del>-</del>			