Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT   P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION	V DIVISION WELL API NO.
P.O. Box 2088  DISTRICT II Santa Fe, New Mexico 8	30-025-32442
P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELL	s ////////////////////////////////////
( DC) NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM	
(FORM C-101) FOR SUCH PROPOSALS.)	Ernest C Adkins
1. Type of Well: OIL GAS WELL X OTHER	
2. Name of Operator	8. Well No.
ARCO OIL AND GAS COMPANY  3. Address of Operator	9. Pool name or Wildcat
P. O. Box 1610, Midland, Texas 79702	Eumont Yates/SR/Queen
4. Well Location  Unit Letter $\frac{J}{}$ : $\frac{2160}{}$ Feet From The ${}$ South	Line and 1650 Feet From The East Line
Section 9 Township 21S Range	245
10. Elevation (Show whether De	e initialiti which is a country
3577 GR	
11. Check Appropriate Box to Indicate Na	-
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TELEPOPARILY ARABIDON	[V]
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. $oxedown^{ ext{X}}$ PLUG AND ABANDONMENT $oxedown$
	COMMENCE DRILLING OPNS. A PLUG AND ABANDONMENT L
PULL OR ALTER CASING	CONTRACTOR STREETING OF NO.
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.	CASING TEST AND CEMENT JOB  OTHER:  give pertinent dates, including estimated date of starting any proposed
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and	CASING TEST AND CEMENT JOB  OTHER:  give pertinent dates, including estimated date of starting any proposed  8-5/8" 24# csg to 403". Cmt'd w/350 sx o surf. WOC 10-1/2 hrs. Est comp
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.  Spud 12-1/4" hole 4-2-94. TD'd @ 403'. Ranging!" + 2% cc + 1/4# CS (yld 1.32). Circ cmt to	CASING TEST AND CEMENT JOB  OTHER:  give pertinent dates, including estimated date of starting any proposed  8-5/8" 24# csg to 403'. Cmt'd w/350 sx o surf. WOC 10-1/2 hrs. Est comp 30 min. DA with 7-7/8" bit.  15.5# csg to 3700'. Cmt'd w/600 sx ed by 250 sx C + 1/4# CF (yld 1.32).
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.  Spud 12-1/4" hole 4-2-94. TD'd @ 403'. Rangular + 2% cc + 1/4# CS (yld 1.32). Circ cmt to strength 1500#. Press test csg to 1200# for  TD'd 7-7/8" hole @ 3700', 4-6-94. Ran 5-1/2' Poz "C" + 6% gel + 1/4# CF (yld 1.92) follower Pmpd cmt. Dropped plug. Displaced 9 bbls &	CASING TEST AND CEMENT JOB  OTHER:  give pertinent dates, including estimated date of starting any proposed  8-5/8" 24# csg to 403'. Cmt'd w/350 sx o surf. WOC 10-1/2 hrs. Est comp 30 min. DA with 7-7/8" bit.  15.5# csg to 3700'. Cmt'd w/600 sx ed by 250 sx C + 1/4# CF (yld 1.32). cmt bridged off. Did not circ cmt.
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.  Spud 12-1/4" hole 4-2-94. TD'd @ 403'. Rangular + 2% cc + 1/4# CS (yld 1.32). Circ cmt to strength 1500#. Press test csg to 1200# for  TD'd 7-7/8" hole @ 3700', 4-6-94. Rangular 5-1/2' Poz "C" + 6% gel + 1/4# CF (yld 1.92) followed Pmpd cmt. Dropped plug. Displaced 9 bbls & RR 4-6-94.	CASING TEST AND CEMENT JOB  OTHER:  give pertinent dates, including estimated date of starting any proposed  8-5/8" 24# csg to 403'. Cmt'd w/350 sx o surf. WOC 10-1/2 hrs. Est comp 30 min. DA with 7-7/8" bit.  15.5# csg to 3700'. Cmt'd w/600 sx ed by 250 sx C + 1/4# CF (yld 1.32). cmt bridged off. Did not circ cmt.  63-3675' PBD.  Ran GR/CNL/CCL from 3651-2090'.
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.  Spud 12-1/4" hole 4-2-94. TD'd @ 403'. Ran "C" + 2% cc + 1/4# CS (yld 1.32). Circ cmt t strength 1500#. Press test csg to 1200# for  TD'd 7-7/8" hole @ 3700', 4-6-94. Ran 5-1/2'. Poz "C" + 6% gel + 1/4# CF (yld 1.92) followed Pmpd cmt. Dropped plug. Displaced 9 bbls & RR 4-6-94.  4-7-94 - RUPU. RU Reverse unit. DOC from 25 del 2-94 - Press test csg to 1000# for 30 min  Ran GR/CBL from 3651-700'. TOC @ 9	CASING TEST AND CEMENT JOB  OTHER:  give pertinent dates, including estimated date of starting any proposed  8-5/8" 24# csg to 403'. Cmt'd w/350 sx o surf. WOC 10-1/2 hrs. Est comp 30 min. DA with 7-7/8" bit.  15.5# csg to 3700'. Cmt'd w/600 sx ed by 250 sx C + 1/4# CF (yld 1.32). cmt bridged off. Did not circ cmt.  3-3675' PBD.  Ran GR/CNL/CCL from 3651-2090'.
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.  Spud 12-1/4" hole 4-2-94. TD'd @ 403'. Rangi'c" + 2% cc + 1/4# CS (yld 1.32). Circ cmt to strength 1500#. Press test csg to 1200# for  TD'd 7-7/8" hole @ 3700', 4-6-94. Rang 5-1/2' Poz "C" + 6% gel + 1/4# CF (yld 1.92) followed Pmpd cmt. Dropped plug. Displaced 9 bbls & RR 4-6-94.  4-7-94 - RUPU. RU Reverse unit. DOC from 2544-12-94 - Press test csg to 1000# for 30 min. Ran GR/CBL from 3651-700'. TOC @ 94451-148 from 3651-700'. TOC @ 94551-148 from 3651-700'.	CASING TEST AND CEMENT JOB  OTHER:  give pertinent dates, including estimated date of starting any proposed  8-5/8" 24# csg to 403'. Cmt'd w/350 sx o surf. WOC 10-1/2 hrs. Est comp 30 min. DA with 7-7/8" bit.  15.5# csg to 3700'. Cmt'd w/600 sx ed by 250 sx C + 1/4# CF (yld 1.32). cmt bridged off. Did not circ cmt.  33-3675' PBD.  Ran GR/CNL/CCL from 3651-2000'.  32'. RDPU.
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.  Spud 12-1/4" hole 4-2-94. TD'd @ 403'. Ranging + 2% cc + 1/4# CS (yld 1.32). Circ cmt to strength 1500#. Press test csg to 1200# for TD'd 7-7/8" hole @ 3700', 4-6-94. Ranging 5-1/2' Poz "C" + 6% gel + 1/4# CF (yld 1.92) followed Pmpd cmt. Dropped plug. Displaced 9 bbls & RR 4-6-94.  4-7-94 - RUPU. RU Reverse unit. DOC from 25 del 12-94 - Press test csg to 1000# for 30 min. Ranging GR/CBL from 3651-700'. TOC @ 9	CASING TEST AND CEMENT JOB  OTHER:  give pertinent dates, including estimated date of starting any proposed  8-5/8" 24# csg to 403'. Cmt'd w/350 sx o surf. WOC 10-1/2 hrs. Est comp 30 min. DA with 7-7/8" bit.  15.5# csg to 3700'. Cmt'd w/600 sx ed by 250 sx C + 1/4# CF (yld 1.32). cmt bridged off. Did not circ cmt.  33-3675' PBD.  Ran GR/CNL/CCL from 3651-2090'.  32'. RDPU.
PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.  Spud 12-1/4" hole 4-2-94. TD'd @ 403'. Ranger of the strength 1500#. Press test csg to 1200# for TD'd 7-7/8" hole @ 3700', 4-6-94. Ranger of 1200# for TD'd 7-7/8" hole @ 3700', 4-6-94. Ranger of 1200# Ppz "C" + 6% gel + 1/4# CF (yld 1.92) followed Pmpd cmt. Dropped plug. Displaced 9 bbls & RR 4-6-94.  4-7-94 - RUPU. RU Reverse unit. DOC from 25 delicated of the state of the state of the lost of my knowledge and be SKONATURE ** ** ** ** ** ** ** ** ** ** ** ** **	CASING TEST AND CEMENT JOB  OTHER:  give pertinent dates, including estimated date of starting any proposed  8-5/8" 24# csg to 403'. Cmt'd w/350 sx o surf. WOC 10-1/2 hrs. Est comp 30 min. DA with 7-7/8" bit.  15.5# csg to 3700'. Cmt'd w/600 sx ed by 250 sx C + 1/4# CF (yld 1.32). cmt bridged off. Did not circ cmt.  33-3675' PBD.  Ran GR/CNL/CCL from 3651-2000'.  32'. RDPU.