<form></form>	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Ibispose Water (Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.) starting any proposed work. If well is
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals SUBMIT IN TRIPLICATE Type of Well Gas INJECTION Other CONOCO INC. Address and Telephone No. 10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Footage. Sec., T., R., M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Notice of Intent K Subsequent Report Final Abandonment Notice Z009/96 MIRU, POH laying down 144 - 3/4" rods, pump.POH wftubing. Rith w/ RBP and set at 3380	Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. LC 031740A 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation 8. Well Name and No. Meyer A-1 WELL \$ 21 9. API Well No. 30-025-32480 10. Field and Pool, or Exploratory Area Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM 2. OTHER DATA Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion or Recompletion or Nell Scompletion or Nell Scompletion or Recompletion or Nell Scompletion or Nell Scomplet
BUREAU OF LAND MANAGEMENT SUDDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	Expires: March 31, 1993 5. Lease Designation and Serial No. LC 031740A 6. If Indian, Alkottee or Tribe Name 7. If Unit or CA, Agreement Designation 8. Welf Name and No. Meyer A-1 WELL \$21 9. API Well No. 30-025-32480 10. Field and Pool, or Exploratory Area Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM COTHER DATA Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Starting any proposed work. If well is
SUNDRY NOTICES AND REPORTS ON WELLS Describe Proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals SUBMIT IN TRIPLICATE SUBMIT IN TRIPLICATE Type of Well original of gas INJECTION Well Well Other Name of Operator CONOCO INC. Address and Telephone No. 10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Foolage, Sec. T. R. M. or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF SUBMISSION Orteor for meter Other Subsequent Report Image: Subsequent Report Image: Sec. RBP lower zone Describe Proposed or Completed Operations (Clearly state all perfinent details, and give perfored date, rectioning writed colspan="2">Set RBP lower zone Set RBP lower zone ZO9/06 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing.	5. Lease Designation and Serial No. LC 031740A 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation 8. Welf Name and No. Meyer A-1 WELL \$21 9. API Well No. 30-025-32480 10. Field and Pool, or Exploratory Area Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM 2. OTHER DATA 2. Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals SUBMIT IN TRIPLICATE Type of Well X oil Gas Well Well Well Other Name of Operator Other CONOCO INC. Address and Telephone No. 10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Footage. Sec., T., R., M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Atering Casing Y Final Abandonment Notice Atering Casing X Other Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all performent details, and give perfrent dates, including estimated date- directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 14	 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation 8. Well Name and No. Meyer A-1 WELL # 21 9. API Well No. 30-025-32480 10. Field and Pool, or Exploratory Area Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM Contract of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals SUBMIT IN TRIPLICATE Type of Well X oil Gas Well Well Well Other Name of Operator Other CONOCO INC. Address and Telephone No. 10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Footage. Sec., T., R., M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Atering Casing Y Final Abandonment Notice Atering Casing X Other Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all performent details, and give perfrent dates, including estimated date- directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 14	
Use "APPLICATION FOR PERMIT" for such proposals SUBMIT IN TRIPLICATE Type of Well	
SUBMIT IN TRIPLICATE Type of Well INJECTION Well Other Name of Operator CONOCO INC. Address and Telephone No. 10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Footage, Sec., T., R., M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Casing Repair Subsequent Report Plugging Back Casing Repair Attering Casing To: Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	
X Oil Gas INJECTION Weil Other Other Name of Operator CONOCO INC. Address and Telephone No. 10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Weil (Footage, Sec., T., R. M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Recompletion X Subsequent Report Final Abandonment Notice Attering Casing Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Meyer A-1 WELL # 21 9. API Well No. 30-025-32480 10. Field and Pool, or Exploratory Area Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM COTHER DATA Conversion Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Starting any proposed work. If well is
Weil Other Name of Operator CONOCO INC. Address and Telephone No. 10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Footage, Sec., T., R., M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Meyer A-1 WELL # 21 9. API Well No. 30-025-32480 10. Field and Pool, or Exploratory Area Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM COTHER DATA Conversion Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Starting any proposed work. If well is
Name of Operator CONOCO INC. Address and Telephone No. 10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Footage, Sec., T., R., M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Attering Casing X Other Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date driver durectionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Meyer A-1 WELL # 21 9. API Well No. 30-025-32480 10. Field and Pool, or Exploratory Area Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM COTHER DATA Conversion Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Starting any proposed work. If well is
Address and Telephone No. 10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Footage, Sec., T., R., M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Recompletion X Subsequent Report Final Abandonment Notice Altering Casing X Other Set RBP lower zone Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	9. API Well No. 30-025-32480 10. Field and Pool, or Exploratory Area Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM COTHER DATA Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is
10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Footage, Sec., T., R., M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Subsequent Report Plugging Back Final Abandonment Notice Attering Casing Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	10. Field and Pool, or Exploratory Area Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM COTHER DATA Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.) starting any proposed work. If well is
Location of Well (Footage, Sec., T., R. M., or Survey Description) SURFACE: 990' FSL & 660' FWL, SEC. 17, T 21S, R 36E, UNIT LTR 'M' TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Subsequent Report Final Abandonment Notice Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Eumont Yates 7 Rvrs. Qn. (Pro Gas 11. County or Parish, State LEA, NM COTHER DATA Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.) starting any proposed work. If well is
TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF SUBMISSION Abandonment Abandonment Abandonment Recompletion Subsequent Report Final Abandonment Notice Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	
TD: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF SUBMISSION Abandonment Abandonment Abandonment Recompletion Subsequent Report Final Abandonment Notice Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	LEA, NM COTHER DATA Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.) starting any proposed work. If well is
TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Notice of Intent Recompletion X Subsequent Report Plugging Back Final Abandonment Notice Attering Casing X Other Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.) starting any proposed work. If well is
TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Notice of Intent Recompletion X Subsequent Report Final Abandonment Notice Plugging Back Casing Repair Attering Casing X Other Set RBP lower zone Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Ibispose Water (Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.) starting any proposed work. If well is
Notice of Intent Abandonment Recompletion Recompletion X Subsequent Report Plugging Back Casing Repair Attering Casing Final Abandonment Notice Attering Casing X Other Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	New Construction Non-Routine Fracturing Vater Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.) starting any proposed work. If well is
Recompletion Recompletion Recompletion Plugging Back Casing Repair Final Abandonment Notice Final Abandonment Notice Set RBP lower zone Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	New Construction Non-Routine Fracturing Vater Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.) starting any proposed work. If well is
X Subsequent Report Plugging Back Casing Repair Casing Repair Final Abandonment Notice Attering Casing X Other Set RBP lower zone Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.) starting any proposed work. If well is
Einal Abandonment Notice Casing Repair Altering Casing Attering Casing Attering Casing X Other Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Water Shut-Off Conversion to Injection Dispose Water (Note Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is
Final Abandonment Notice Attering Casing X Other Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is
X Other Set RBP lower zone Orecompleted Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	(Note: Report results of multiple completion on Well (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is
Set RBP lower zone Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	Completion or Recompletion Report and Log form.) starting any proposed work. If well is
directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this 2/09/96 MIRU. POH laying down 144 - 3/4" rods, pump.POH w/tubing. RIH w/ RBP and set at 3380	starting any proposed work. If well is
	APR 15 TOGS
I hereby certify that the foregoing a true and correct Signed Ann E. Ritchie REGULATORY AGENT (This space for Federal or State office use) pproved by Conditions of approval, if any	
18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United	Date 04/08/96
ements or representations as to any matter within its jurisdiction. *See Instruction on Reverse Side	Date Armoo

•

