

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer 44, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		API NO. (Assigned by OCD on New Wells) 30-025-32788 32827
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator CHEVRON U.S.A. INC.		6. State Oil & Gas Lease No. N/A
3. Address of Operator P.O. BOX 1150 ATTN: P.R. MATTHEWS		7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT
4. Well Location Unit Letter 1980 : WEST Feet From The 560' Line and SOUTH Feet From The 36 Line Section 35 Township 21S Range 36 NMPM LEA County		8. Well No. 138
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3578' GL		9. Pool name or Wildcat GRAYBURG

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: DRILLING SUMMARY <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU V&B RIG #1 ON 1-10-95, SPUDDER WELL AT 16:00 HRS.
DRILLED 12.25" HOLE TO 1467'. SET 8 5/8" M-50 23# CASING TO 1467'.
WOC FOR 12 HRS., TEST CASING TO 1000 PSI-OK.
DRILL OUT SHOE WITH 7 7/8" BIT TO TD AT 4060'.
LOG HOLE WITH DUAL LATERAL & COMP. NEUTRON LOGS.
SET 5 1/2" K-55, 15.5 # CASING TO 4060'.
NU WELLHEAD AND TEST - OK.
RDMO ON 1-16-95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	<u>P.R. Matthews</u>	TITLE	TECHNICAL ASSISTANT
DATE:		1/18/95	
TYPE OR PRINT NAME		P.R. MATTHEWS	
TELEPHONE NO.		(915) 687-7812	
APPROVED BY	<u>Paul Korte</u>	TITLE	Geologist
DATE		JAN 24 1995	
CONDITIONS OF APPROVAL, IF ANY:			

15