

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N OIL CONS. COMMISSION  
P.O. BOX 1980  
HOBBS NEW MEXICO 88240

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Pogo Producing Company

3. Address and Telephone No.

P. O. Box 10340 Midland TX 79702-7340 (915/682-6822)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310' FSL & 760' FEL of Section 25, T-21-S, R-32-E

5. Lease Designation and Serial No.

NM-86145

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Axe 25 Federal #1

9. API Well No.

30-025-33318

10. Field and Pool, or Exploratory Area

Wildcat

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water


(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Drilled 6-3/4" hole to 9100'. TD reached @ 0030 hrs CST 3/20/96. Logged well with Western Atlas. Logs indicate poor reservoir. Pogo request permission to set plugs as per procedure below and P&A the above well based on recommendation via telephone with Vance Balderaz with the BLM in Hobbs

Spot 50 sx Cl "C" cement plug f/8980'-8600'  
Spot 50 sx Cl "C" cement plug f/6650'-6350'  
Spot 50 sx Cl "C" cement plug f/4988-4888'  
Spot 50 sx Cl "C" cement plug f/858'-658  
Spot 50 sx Cl "C" cement plug f/20' - surface

Cut off wellhead and install P&A marker.



14. I hereby certify that the foregoing is true and correct

Signed

*[Signature]*

Title Senior Operations Engineer

Date 3/20/96

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

*[Handwritten mark]*