Submit 3 Copies to Appropriate District Office

State of New Mexico rgy, Minerals and Natural Resources Departm

Form C	-103
Revised	1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION INVESTIGABLE

DISTRICT II

CONDITIONS OF APPROVAL, IF ANY:

		- 0,
10.		

P.O. Drawer DI), Art	esia,	NM	882	210	
DISTRICT III						

P.O. Box 2088 Santa Fe, New Mexico 87504-2088	30-025-33439	
	5. Indicate Type of Lease STATE X	FEE _

DISTRICT III			STATE X F	EE [
	x Rd., Aziec, NM 87410		6. State Oil & Gas Lease No.	
	SUNDRY NOTICES AND REPORTS ON WE	118		7777.
(DO NOT US	SE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEI	NOR PLUG BACK TO A		
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PE (FORM C-101) FOR SUCH PROPOSALS.)	ERMIT"	7. Lease Name or Unit Agreement Name	
I. Type of We	ell:		Exxon Fee	
METT X	WELL OTHER			
Name of Op			8. Well No.	
	Resources, Inc.		1	
3. Address of	•		9. Pool name or Wildcat	
4. Well Location	0. Box 5061, Midland, TX 79704	 	Drinkard	
		Line and1980	Feet From The East	Lin
Section	n 4 Township 21S R	nee 07H	AD COM A	
	10 Elevation (Show whether	inge 37E DF, RKB, RT, GR, etc.)	NMPM Lea c	County
	//////////////////////////////////////			
11.	Check Appropriate Box to Indicate 1	Nature of Notice, Re	POORL OF Other Data	
	NOTICE OF INTENTION TO:	i .	SEQUENT REPORT OF	
		000	DEGOERT TIET ONT OF:	
	IEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
EMPORARILY		COMMENCE DRILLING	OPNS. PLUG AND ABANDONMI	ENT
ULL OR ALTER	R CASING	CASING TEST AND CE	MENT JOB	
THER: Rec	complete, set RBP above Blinebry X	OTHER:		[
 Describe Prop work) SEE F 				
3/22/96	Well was completed $8/22/96$. $8-5/8$	@ 1245', cmted	w/750 sxs C1. C & circ.	
	5-1/2" @ 7100', cmted w/400 sxs CL 1	1.8500 sxs 65/3	5 Poz & 300 sxs CL C, circ	•
	Perfs: 6682-6819', 19 holes, & 655	3 = 6570', 12 hole	s. Acidized W/3500 g. 15%	
	NEFE (6682-6819) and perfs 6553-6579	J, acidized W/25	OU gais 13% NEFE.	
0.122.106	POT: 20 BO, 116 MCF, 149 BW. Set bridge plug @ 6450'. Perf 1 sp.	f 5820-37' and 5	916-26'. Spotted 3000 gal	s
.0/22/96	15% NEFE & frac'd w/40,000 gals Dela	ta frac w/96.500	# $16/30$ sd. Ran 2- $7/8$ " tb	g.
	w/SN @ 6036. Pumping rate 25 BO, 30		20, 20 222	O
/07/97	Propose to dump 35' cmt on CIBP @ 6	755'. Set CIBP	@ 6450' & dump 35' of cmt	on
	top. Set RBP @ 5535'. Circ hole w	/2% KCL & test c	sg & RBP. Propose to perf	
	1 spf 4227',28',32',46',49', 4250',	55',64',69',72',	80',82',88',93',4300',09',	11',
	28',31',32',48',54',4362',68',73',7	8',83', and 4388	', total 28 holes. Will	
	stimulate as needed & return well t		ing on weather to do work)	
I hereby centify that	t the information above is true and complete to the best of my knowledge and b	odia.		
KONATURE	Janie Courtney m	E Regulatory	Tech DATE 1/10/97	
TYPE OR PRINT NM	1		915/685-176 TELEPHONE NO.	1
Thus space for State	e Use)			
,	*		JAN 16 193	37
PPROVED BY	тти	F		21
	1112		UAIE	



Submit 3 Copies to Appropriate District Office

State of New Mexico 39, Minerals and Natural Resources Departme F

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISIO P.O. Box 2088	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	30-025-33439 5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410	STATE FEE X
	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	O A 7. Lease Name or Unit Agreement Name
I. Type of Well: OIL GAS WELL OTHER	Exxon Fee
2. Name of Operator SDX Resources, Inc.	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
P. O. Box 5061, Midland, TX 79704	Drinkard_ (19190)
	1980 Feet From The East Line
	Feet From The Line
Section 4 Township 21S Range 37E 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM Lea County
//////////////////////////////////////	
11. Check Appropriate Box to Indicate Nature of Notice	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL	LING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AN	
	s in Blinebry
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 	-
10/22/96 - MIRU DA&S unit. TOH w/rods & pump. Set brid hole w/2% KCl & test BP & csg, OK. TOH, RU 0 5820-37' and 5916-26'. Spotted acid across process of 15% NEFE. RU Halliburton, frac'd well w/40,0 16/30 Ottowa sd. ND frac valve & NU BOP. To of tbg below SN. Ran 189 jts of 2-7/8" tbg, rods and started pumping back load.	Computalog and perforated 1 spf perfs. Total acid 3,000 gals. 000 gals Delta frac w/96,500# FIH w/retrieving head on 1 jt
10/31/96 Pumping rate 25 BO, 30 BW, & 143 MCF.	
I hereby cerufy that the information above is true and complete to the best of my knowledge and belief.	Took 11/15/00
SIONATURE Regulatory	DATE
TYPEORPRINT NAME Janice Courtney	915/685/1761 TELEPHONE NO.
Thus space for State Use)	
CROST CONTROL	NOV 19 199 6

- DATE -

CONDITIONS OF APPROVAL, IF ANY: