

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-34590</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name <b>PRAIRIE FIRE STATE</b>
2. Name of Operator <b>Phillips Petroleum Company</b>	8. Well No. <b>1</b>
3. Address of Operator <b>4001 Penbrook Street Odessa, TX 79762</b>	9. Pool name or Wildcat <b>OSUDO WEST (MORROW) #82240</b>
4. Well Location Unit Letter <b>7</b> : <b>1980</b> Feet From The <b>NORTH</b> Line and <b>1650</b> Feet From The <b>EAST</b> Line Section <b>2</b> Township <b>21-S</b> Range <b>34-E</b> NMPM <b>LEA</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3710' G.L., 3733' K.B.</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05/20/99 Drllg. w/motor 9945-10268'. lost 200 psi pump psi, trip out for hole in pipe.  
05/21/99 FIN trip out for hole in pipe, change out motor, trip in hole, drill  
10268-10560'. built 1200 bbls. aphron mud to use at mud up.  
05/22/99 Drill & svy. 10560-10842'. Developed hole in drill pipe, trip out for hole  
in pipe at DC's at rpt. time.  
05/23/99 FIN trip out, test BOPE, TIH w/16.6# DP, POOH & LD 16.6# DP, PU 16.6# DP f/  
racks, TIH, drill 10842-10875'.  
05/24/99 Drill 10875-11106'/displaced hole w/10 ppg Aphron mud @ 11106'.  
05/25/99 Drill 11106-11185'-trip for bit & L/D motor-RIH to csg shoe-cut and slip  
drill line. (bit 1/4" out of gauge)  
05/26/99 Finish cut & slip drill line-RIH to 11095'-wash and ream to bottom.  
Drill 11185-11201'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Larry M. Sanders* TITLE SUPV., REGULATION/PRORATION DATE 06/08/99  
TYPE OR PRINT NAME Larry M. Sanders TELEPHONE NO. (915) 368-1488

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS  
DISTRICT I FIELD OFFICE

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUN 10 1999

CONDITIONS OF APPROVAL, IF ANY: