Energy, Minerals and Natural Resources Revised Murch 25, 1999	Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103		
District		Energy, Minerals and Natural Resources					
\$1 South First, Artesia, NM 87210 Otto CONSERVATION DIVISION District II Otto Robert Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS CON NOT USE THIS FORM FOR PROPOSALS TO DEBLIL OR TO DEBPEN OR PLUG BACK TO A DEFERDANT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: Oil Well Gas Well [X] Other Unit Letter O					1		
District District District County District		OIL CONSERVATION DIVISION				oe of Lease	
Santa Fe, NM 8/50S G. State Oil & Gas Lease No.							
SUNDRY NOTICES AND REPORTS ON WELLS DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH MARY State "12" Com Mary	District IV	Santa re, inivi 8/303					
CONDITION TO USE THIS FORM FOR PROPOSALS TO DEEPEN OR PELLE BACK TO A DEFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS). Type of Well: Oil Well							
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS! Oil Well					Lease Name or Unit Agreement Name:		
PROPOSALS) Oil Well	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Mary State "12" Com		
Oil Well Gas Well (X) Other Name of Operator Well No.	•	1/101/ 01000 12					
2. Name of Operator Matador Operator		▼ Other					
3. Address of Operator 3.340 Meadow Rd., #158, Dallas, TX 75231 4. Well Location Unit Letter O					Well No.		
Well Location Unit Letter_O					j -		
Unit Letter_O : 660 _ feet from the _south _ line and _ 1980 _ feet from the _east _ line Section 12							
Unit Letter O : 660 _ feet from the _south _ line and _ 1980 _ feet from the _east _ line Section 12					Wilson Morrov	<u>v</u>	
Section 12 Township 21S Range 34E NMPM Lea County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3869 'GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING ALTERING CASING PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB CEMENT JOB	4. Well Location						
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3869 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ +6% CaCI2 + 25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wrt). Tail: 275 sx class "C" + 2% CaCI2 (14.80 PPG, 1.34 yld, 6.30 GPS wrt). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	Unit LetterO:	660feet from the	_south	line and1980)feet fro	om the _eastline	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ + 6% CaCl2 + 25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wrr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wrr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	Section 12	Township 2	21S I	Range 34E	NMPM L	ea County	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ +6% CaCl2 + .25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wtr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Aukford Title Production Analyst DATE 3-7-0 / Type or print name Patti Lankford Telephone No. 214-987-7130 (This space for State use) APPPROVED BY TITLE DATE			vhether DI	R, RKB, RT, GR, etc.)		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ + 6% CaCl2 + .25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wtr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE							
PERFORM REMEDIAL WORK PLUG AND ABANDON CALABORDON ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CEMENT JOB OTHER: DATE 3-7-0 / Type or print name Patti Lankford CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: CASING TEST AND CEMENT JOB OTHER: O			uicale Na				
TEMPORARILY ABANDON							
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: DITER: OTHER: OTHER: OTHER: Indicate of starting any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ + 6% CaCl2 + .25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wtr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Start. Lawkford TITLE Production Analyst DATE 3-7-0 / Type or print name Patti Lankford Telephone No. 214-987-7130 Thereby certify that the information above is TITLE DATE TITLE DATE APPPROVED BY TITLE DATE	PERFORM REMEDIAL WORK	FLOG AND ADANDON		TEMEDIAL WORK	`	1 /12/2/11/10 0/10/10	
OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ + 6% CaCl2 + .25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wtr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE DATE January Jan	TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	LING OPNS. 🔀		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ + 6% CaCl2 + .25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wtr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	PULL OR ALTER CASING			E.	D 🗵	3	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ + 6% CaCl2 + .25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wtr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	OTHER:			OTHER:			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ + 6% CaCl2 + .25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wtr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE		ed operations (Clearly s	tate all per	-	ive pertinent dat	es, including estimated date	
Spudded 17-1/2" hole 2/21/01. Drilled to 1422' and ran 32 jts 13-3/8" 48# H-40 STC csg. Set @ 1422'. Cemented w/ lead: 760 sx Class "C" 35:65 POZ + 6% CaCl2 + .25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wtr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	of starting any proposed work)	. SEE RULE 1103. For	Multiple (Completions: Attach	wellbore diagra	ım of proposed completion	
Class "C" 35:65 POZ + 6% CaCl2 + .25 Polyflake (12.40 PPG, 20.7 yld, 11.51 GPS wtr). Tail: 275 sx class "C" + 2% CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	-		. 10.0/01	40 U TT 40 CTC	0 + (2) 14222	C	
CaCl2 (14.80 PPG, 1.34 yld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd. NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	Spudded 17-1/2" hole 2/21/01. Dr	illed to 1422 ' and ran 32 j % $C_2C_{12} + .25$ Polyflake	ts 13-3/8"	48# H-40 STC csg.	Set @ 1422'. (Demented w/ lead: 700 sx 275 sy class "C" + 2%	
NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	CaCl2 (14 80 PPG, 1.34 vld, 6.30 GPS wtr). Circ 255 sx to pit. Job complete 2-26-01. WOC. Cut off csg & weld on csghd.						
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Satte Sankford TITLE Production Analyst DATE 3-7-0 / Type or print name Patti Lankford Telephone No. 214-987-7130 (This space for State use) APPPROVED BY TITLE DATE	NU 13-5/8" BOPE & test blind rams to 500 psi, OK. Drill cement and resume drilling 12-1/4" hole in formation.						
SIGNATURE Satte Lankford Type or print name Patti Lankford Telephone No. 214-987-7130 (This space for State use) APPPROVED BY TITLE DATE DATE		_					
Type or print name Patti Lankford TITLE Production Analyst DATE 3-7-0/ (This space for State use) APPPROVED BY TITLE DATE							
SIGNATURE Satte Lankford Type or print name Patti Lankford Telephone No. 214-987-7130 (This space for State use) APPPROVED BY TITLE DATE DATE							
Type or print name Patti Lankford TITLE Production Analyst DATE 3-7-0/ (This space for State use) APPPROVED BY TITLE DATE							
SIGNATURE Satte Lankford Type or print name Patti Lankford Telephone No. 214-987-7130 (This space for State use) APPPROVED BY TITLE DATE DATE							
Type or print name Patti Lankford Telephone No. 214-987-7130 (This space for State use) APPPROVED BY TITLE DATE	I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
(This space for State use) APPPROVED BY TITLE DATE	SIGNATURE Patti L	Enkford	_TITLE_	Production Analy	yst	DATE <u>3-7-0/</u>	
APPPROVED BY	Type or print name Patti Lan	kford			Telephone	No. 214-987-7130	
ATTROVED DT	(This space for State use)					W. T. W. C. L.	
		*	_TITLE		· · · · · · · · · · · · · · · · · · ·	DATE	