

Submit 3 Copies To Appropriate District
Office
District I
1623 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-35246
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator Xaric Oil & Gas Corporation		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 352 Midland, Texas 79702		7. Lease Name or Unit Agreement Name: Jones Robinson
4. Well Location Unit Letter <u>0</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>19</u> Township <u>20S</u> Range <u>39E</u> NMPM County <u>Lea</u>		8. Well No. #1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3560 GR		9. Pool name or Wildcat DK Drinkard

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: Test Drinkard ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/5/01 MIRU - Set CIBP @ 7300'; perf Drinkard formation from 7100' - 7126' w/2 SPF total of 36 holes; set Pkr @ 7023'; Test Lower Drinkard before completing Upper Drinkard; making 2 BO; 6 MCF; 55 BW

6/22/01 RIH w/CIBP; set plug @ 7090; perf Drinkard formation from 7028' - 7066'; 4 SPF total 34 holes; Test Upper Drinkard; 3 BO; 6 MCF; 46 BW

8/10/01 Squeeze upper perms 7028'-7066' and drilled out CIBP @ 7090'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Glenda Hunt TITLE Senior Production Analyst DATE 10/17/01

Type or print name Glenda Hunt

(This space for State use)

ORIGINAL SIGNED BY

PAUL E. KATZ

TITLE REGISTERED ENGINEER

(915) 683-3171
Telephone No.

APPROVED BY

DATE

Conditions of approval, if any:

2A DK Abc