		1 Contraction of the second se				
ubmit 3 Copies to Approriate Di	strict	State of New Me				
Office		Energy, Minerals and Nat	ural Resouces			FORM
DISTRICT I					Revised	FORM C- March 25, 1
625 N. French Dr., Hobbs, NM	88240	OIL CONSERVATION	NDIVISION	WELL API NO.	1001300	
DISTRICT II	110	1220 South St. France		30-025-3	35765	
11 South First, Artesia, NM 882	.10	Santa Fe, NM 8		5. Indicate Type of Lea		
DISTRICT III 000 Rio Brazos Rd., Aztec, NM	87410	Santa i C, i Vivi O	1505		✓ STATE	FEE
DISTRICT IV				6. State Oil & Gas Leas		
220 South St. Francis Dr., Santa	Fe, NM 87505					
S	UNDRY NOTICES	AND REPORTS ON WEL	LLS			
(DO NOT USE THIS FO	RM FOR PROPOSALS T	O DRILL OR TO DEEPEN OR	PLUG BACK TO A	7. Lease Name or Unit	Agreement Name	
	IR. USE "APPLICATION	N FOR PERMIT" (FORM C-101) FOR SUCH		State DA	
PROPOSALS.)		<u> </u>		-	State DA	
□. Type of well: OIL WE	LL 🔲 GAS WI					
				8. Well No.		,
2. Name of Operator	,			S. HOATIG.	8	
Apache Corporation 3. Address of Operator				9. Pool name or Wilde		
2000 Post Oak Blvd	I., Ste. 100, Houston,	Texas 77056-4400				
		a a	Line and 2200	Paat Brown The-	East Line	
Unit Letter	J : 1980			Feet From The		
Section	16 Township		PT GP mmp	м Lea	County	
		10. Elevation (Show whether DF, RKB, 3456' GR	л ι, υπ, <i>ειс.)</i>			
			to Indicate Nature of Not	ice, Report. or Othe	r Data	
11. NO	TICE OF INTENTION			BSEQUENT REP		
110			1 _	-	_	
Perform Remedia	al Work 🛛 P	lug and Abandon	Remedial Wor	k	Altering	Casing
Temporarily Aba	ndon 🗖 c			illing Operations	Plug and	Abandonment
		nange Plans	I UI Commence Dr			
		Change Plans				
Pull or Alter Cas		nange Plans	Casing Test ar			
Other	ing	-	Casing Test ar	nd Cement Job Surface & Pro	oduction Casing	
Other 12. Describe propose	ng d or completed operatio	ons. (Clearly state all pertiner ILE 1103. For Multiple Com	Casing Test ar	nd Cement Job Surface & Pro	oduction Casing	
Other 12. Describe propose of starting any pr	d or completed operatio oposed work). SEE RU MIRU Capstar Rig	ons. (Clearly state all pertiner	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellboom om. Drilled 12-1/4" h	nd Cement Job Surface & Pro nent dates, includi ore diagram of pro	ing estimated date	
Other Other Other Of starting any pr or recompletion.	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& (5 POZ "C" ∂
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& (5 POZ "C" ∂
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& (5 POZ "C" ∂
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& (5 POZ "C" ∂
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& (5 POZ "C" ∂
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& C 5 POZ "C" &
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& C 5 POZ "C" &
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& C 5 POZ "C" &
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& (5 POZ "C" ∂
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& (5 POZ "C" ∂
Other Other Of starting any pr or recompletion. 12/7/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C".	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& C 5 POZ "C" &
Other Describe propose of starting any pr or recompletion. 12/7/2001 12/13/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C". (Released rig @ 7:0	ns. (Clearly state all pertiner TLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T 0 am.	Casing Test ar Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" h ulated 76 sx to pit 2" 17# J-55 LT&C cas	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6	≠ J-55 ST& C 5 POZ "C" &
Other Describe propose of starting any pr or recompletion. 12/7/2001 12/13/2001 I hreeby certify that the information	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C". (Released rig @ 7:0	ns. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T	Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" have ulated 76 sx to pit 2" 17# J-55 LT&C cas Cop of float collar @ 4	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ram sing. Cemented 1110'. Top of flo	oduction Casing ing estimated date posed completion 1 9 jts 8-5/8" 24# w/ 1050 sx 35/6 pat shoe @ 4199	# J-55 ST& (5 POZ "C" &
Other Describe propose of starting any pr or recompletion. 12/7/2001 12/13/2001	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C". (Released rig @ 7:0	ns. (Clearly state all pertiner TLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T 0 am.	Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" have ulated 76 sx to pit 2" 17# J-55 LT&C cas Cop of float collar @ 4	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ran sing. Cemented	oduction Casing ing estimated date posed completion 1 9 jts 8-5/8" 24# w/ 1050 sx 35/6 pat shoe @ 4199	# J-55 ST& C 5 POZ "C" & ". 12/17/200
Other Describe propose of starting any pr or recompletion. 12/7/2001 12/13/2001 I hreeby certify that the information	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C". (Released rig @ 7:0	ns. (Clearly state all pertiner TLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T 0 am.	Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" have ulated 76 sx to pit 2" 17# J-55 LT&C cas Cop of float collar @ 4	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ram sing. Cemented 1110'. Top of flo	oduction Casing ing estimated date posed completion 1 9 jts 8-5/8" 24# w/ 1050 sx 35/6 pat shoe @ 4199	≠ J-55 ST& C 5 POZ "C" &
Conter Other Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter C	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C". (Released rig @ 7:0	ns. (Clearly state all pertiner TLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T 0 am.	Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" have ulated 76 sx to pit 2" 17# J-55 LT&C cas Cop of float collar @ 4	nd Cement Job Surface & Pro- ment dates, includione diagram of pro- ole to 406'. Ram sing. Cemented 1110'. Top of flo	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6 oat shoe @ 4199	# J-55 ST& C 5 POZ "C" & ". 12/17/200
Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C". (Released rig @ 7:0	ns. (Clearly state all pertiner TLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T 0 am.	Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" have ulated 76 sx to pit 2" 17# J-55 LT&C cas Cop of float collar @ 4	nd Cement Job Surface & Pro- ment dates, includi ore diagram of pro- ole to 406'. Ram sing. Cemented 1110'. Top of flo	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6 oat shoe @ 4199	# J-55 ST& C 5 POZ "C" & ". 12/17/200
Conter Other Conter Content of starting any proor recompletion. Content of starting any proor recompletion. Content of the start of the start of the space for Start Use (This space for Start Use) Content of the space for Start Use (Content of the space for Start Use)	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C". Released rig @ 7:0	ons. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T 0 am.	Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" have ulated 76 sx to pit 2" 17# J-55 LT&C cas Cop of float collar @ 4	nd Cement Job Surface & Pro- ment dates, includione diagram of pro- ole to 406'. Ram sing. Cemented 1110'. Top of flo	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6 oat shoe @ 4199 Cian DATE TELEPHONE NO.	# J-55 ST& C 5 POZ "C" & ". 12/17/200
Conter Other Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C". Released rig @ 7:0	ons. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T 0 am.	Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" have ulated 76 sx to pit 2" 17# J-55 LT&C cas Cop of float collar @ 4	nd Cement Job Surface & Pro- ment dates, includione diagram of pro- ole to 406'. Ram sing. Cemented 1110'. Top of flo	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6 oat shoe @ 4199 cian date 	≠ J-55 ST& C 5 POZ "C" & ". <u>12/17/200</u> 713-296-63
Conter Other Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter Conter	d or completed operatio oposed work). SEE RU MIRU Capstar Rig casing. Cemented Drilled 7-7/8" hole 250 sx Class "C". Released rig @ 7:0	ons. (Clearly state all pertiner JLE 1103. For Multiple Com # 8. Spud well @ 12:00 p w/ 350 sx Class "C". Circ to 4200'. Ran 96 jts 5-1/2 Circulated 115 sx to pit. T 0 am.	Casing Test ar Other at details, and give perting pletions: Attach wellbox om. Drilled 12-1/4" have ulated 76 sx to pit 2" 17# J-55 LT&C cas Cop of float collar @ 4	nd Cement Job Surface & Pro- ment dates, includione diagram of pro- ole to 406'. Ram sing. Cemented 1110'. Top of flo	oduction Casing ing estimated date posed completion a 9 jts 8-5/8" 24# w/ 1050 sx 35/6 oat shoe @ 4199 cian date 	# J-55 ST& C 5 POZ "C" & ". 12/17/200