

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/> FEDERAL <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No.	
FED. # LC-063228	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- SWD Well		7. Unit Agreement Name
2. Name of Operator Estacado, Inc.		8. Farm or Lease Name Fields Federal
3. Address of Operator P. O. Box 5587, Hobbs, New Mexico 88241		9. Well No. 2
4. Location of Well UNIT LETTER M, 990 FEET FROM THE S LINE AND 330 FEET FROM THE W LINE, SECTION 25 TOWNSHIP 23 S RANGE 32 E NMPM.		10. Field and Pool, or WHdcat Triste Draw Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 3713 DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER Pressure Test Csg. & T.A. <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4½" cmt retainer w/bull plug is set at 5000'. Perforated interval 5073-5145' T.D. 5206 PBTD 5185'. Casing was tested above cmt retainer to 500 psi for 15 minutes on 2/15/85 and well was T.A. Propose to again test casing above cmt. retainer to 500 psi and if pressure holds, request an extension of the Temporary Abandonment. If pressure does not hold, a notice of Intention to Abandon will be filed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Donald L. Tarey</u>	TITLE <u>President</u>	DATE <u>July 7, 1988</u>
ORIGINAL SIGNED BY JERRY L. GORDON		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		