

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions on reverse side)Form approved,
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER <u>Salt water Disposal well</u>	5. LEASE DESIGNATION AND SERIAL NO. <u>LC 04 3228</u>
2. NAME OF OPERATOR <u>Continental Oil Company</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P.O. Box 460, Hobbs, New Mexico</u>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>990' FSL ± 330' FWL of Sec. 25, T-23S,</u> <u>R-32E, Lea County, New Mexico</u>	8. FARM OR LEASE NAME <u>Field</u>
14. PERMIT NO.	9. WELL NO. <u>2</u>
15. ELEVATIONS (Show whether DF, RT, GA, etc.) <u>5,713' DF</u>	10. FIELD AND POOL, OR WILDCAT <u>Crow Delaware</u>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 25, T-23S, R-32E</u>
	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>N. Mex.</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Converted to salt water disposal ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, if well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well was converted to a salt water disposal well by the following procedure:

Cleaned out hole from 5087' to 5206' TD. Perforated from 5100' to 5145' with 2 1/2" SPF. Acidized pipe with 2000 gal. 15% HCL acid with ball sealers. Ran plastic lined tubing with injection packer. Set packers at 5095' with 10,000# tension. Ran injection test of 2 bbl. at 100# for 10 minutes. tested OK. Ready to place well on injection 10-23-68

USGS-S FILE: 18. I hereby certify that the foregoing is true and correct

SIGNED W. E. GrierTITLE Adm. Section ChiefDATE 10-27-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

DISTRICT ENGINEER NOV 1 1968

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER