

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-09028</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>Marathon Oil Company</b>		6. State Oil & Gas Lease No. <b>A-2614</b>
3. Address of Operator <b>P.O. Box 2490, Hobbs, NM 88240</b>		7. Lease Name or Unit Agreement Name: <b>South Eunice (7R/Q) Unit</b>
4. Well Location Unit Letter <b>L</b> : <b>1,980</b> feet from the <b>South</b> line and <b>660</b> feet from the <b>West</b> line Section <b>25</b> Township <b>22-S</b> Range <b>36-E</b> NMPM County <b>Lea</b>		8. Well No. <b>#603</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>3,546' GL; 3,556' KB</b>		9. Pool name or Wildcat <b>South Eunice (7R/Q)</b>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

04/09/02 Notified OCD, Sylvia Dickey. MIRU Triple N rig #24. POOH w/ 146 3/4" rods and pump.

04/10/02 Notified OCD, Gary Wink. NU BOP. POOH w/ production tubing. RIH w/ 4 1/2" HM tbg-set CIBP on production tubing. RU cementer, set CIBP @ 3,590'. Circulated hole w/ mud and pumped 25 sx C cmt 3,590 - 3,220'. POOH w/ tbg to 3,100' and pumped 25 sx C cmt w/ 3% CaCl<sub>2</sub> @ 3,100'. POOH w/ tbg to 1,300' and WOC 2 hrs. RIH w/ tbg, tagged cmt @ 2,690'. POOH w/ tbg to 1,300' and pumped 25 sx C cmt 1,300 - 930'. POOH w/ tbg. RIH w/ wireline and perforated casing @ 255', POOH w/ wireline. PU packer, set packer @ 30'. Established circulation to surface. POOH w/ packer and ND BOP. Set packer @ 30' and circulated 60 sx C cmt 255' to surface.

04/19/02 Cut off wellhead, installed dryhole marker. Cut off anchors, backfilled pit & cellar.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James F. Newman TITLE Engineer DATE 04/25/02

Type or print name James F. Newman, P.E. Triple N Services, Inc. Telephone No. 915-687-1994

(This space for State use)

APPROVED BY Carol M. Hill TITLE COMPLIANCE OFFICER DATE JUN 07 2002

Conditions of approval, if any:

COMPLIANCE OFFICER

GWW