NO COPIES RECEIVED		Form C-103
MOLTUELS:	i i i i i i i i i i i i i i i i i i i	Supersedes Old C-102 and C-103
	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1=65
	·	Sa. Indicate Type of Lease
)FFICE		State X Fee
OR		5. State Oil 6 Gas Lease No.
	J	
SUNDR		
GAS WELL WELL	other. Plug & Abandon	7. Unit Agreement Name
Atlantic Richfield Comp	8. Farm or Lease Name McDonald WN State	
3. A cress of Operator		9. Well No.
P. O. Box 1710, Hobbs, New Mexico 88240		10. Field and Pool, or Wildcat
UNIT LETTER F . 1650 FEET FROM THE North LINE AND FEET FROM		Jalmat
THE West LINE, SECTI	ON 25 TOWNSHIP 22S RANGEN	VMPM.
	15. Elevation (Show whether DF, RT, GR, etc.) 3456 GR	12. County Lea
16.		
	Appropriate Box To Indicate Nature of Notice, Report of Subsequence Su	r Other Data JENT REPORT OF:
<u></u>		i
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT [A]
	OTHER	<u> </u>
OTHER		
17. Describe Proposed or Completed O	perations (Clearly state all pentinent details, and give pertinent dates, incl	uding estimated descripturting any proposed
work) SEE RULE 1103.		
csg scraper to 2885'. thru retr w/10 sx & spo- Cut $5\frac{1}{2}$ " csg @ 964' & pu	killed well. Installed BOPs. POH w/complet WIH $w/5\frac{1}{2}$ " cmt retr on tbg, set @ 2880'. Load tted 90 sx on top of retr 2880-2100' w/Cl C clled. Spotted 100 sx Cl C w/3# salt/sk across surface. Installed regulation dry hole many e $3/5/75$.	ded hole w/heavy mud. Cmtd cmt, w/4% gel & 8# salt/sk. ss $5\frac{1}{2}$ " csg stub 964-664'.
Note: Your office to be	e notified when location is ready for inspect	tion.
18. I hereby certify that the information	above is true and complete to the bart of mean owice.	
	A Print Pulls Comm	2/10/75
SIGNED	Dist. Drlg. Supv.	3/10/75
	6)	₹ ₹ €
APPROVED BY	Minyan TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY		