

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instruction.
verse side)

DATE
a re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME <i>South Eunice Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>		8. FARM OR LEASE NAME <i>South Eunice Unit</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460-Hobbs, NM 88240</i>		9. WELL NO. <i>40</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>1980' FNL & 1980' FWL (Unit Letter F)</i>		10. FIELD AND POOL, OR WILDCAT <i>Eunice 7 Rvs Queen South</i>
14. PERMIT NO. <i>30-025-09071</i>		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>28-22S-36E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH <i>Lea</i>
		13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <i>Cleanout & Acidize</i>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work started 2-14-87 and completed 2-22-87. MIRU. POOH w/ rods and pump. Tag at 3790'. Set pkr at 3547'. Test csg to 500 psi. Acidize Seven Rivers Queen w/ 150 bbls 15% HCL-NE-FE acid in three equal stages. Drop 500 lbs. rock salt in 7 bbls gelled brine between stages. Overflush w/ 75 bbls 2% KCl. Grubbed well. POOH w/ Abg & pkr. Hang well on and place on production. Rmpd 23 BO & 72 BW on 3/2/87.

ACCEPTED FOR RECORD

APR 8 1987

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *William D. Finney*

TITLE *ADMIN. SURVEY*

DATE *April 2, 1987*

(This space for Federal or State office use)

APPROVED

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side