

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-030/33(B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

South Eunice Unit

9. WELL NO.

41

10. FIELD AND POOL, OR WILDCAT

Eunice 7 Rurs Queen So.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 28-225-36E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER Injection

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface Unit E

14. PERMIT NO.
30-025-09073

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☐

CHANGE PLANS ☐

(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU, Release pkr @ 3556' & Poot. Clean out to 3804'. (PBTD)
- ② Plug well back from 3804'-3670' w/ 18 ft³ pea gravel. Dump 10' Cal-Seal plug from 3670'-3660'. Set retainer @ 3550'.
- ③ Pump 200 sxs Class "C" w/ 2% CaCl₂. Displace w/ 14 bbls 2% KCL TFW
- ④ WOC 24 hrs. Drill out retainer & cmt to 3660'. Prepare to run in
- ⑤ GIH w/ 4", 10.46# FJ guide shoe, 1 ft 4", 10.46# FJ FL-45 liner, 4", 10.46# FJ float collar, and 4", 10.46# J-55 FJ FL-45 liner. Land guide shoe @ 3655'.
- ⑥ Pump 50 bbls 2% KCL TFW nitrified w/ 180 scf/bbl down liner to establish circ. Pump 100 sxs Class "C" cmt w/ 2% CaCl₂ nitrified w/ 180 scf Na₂/bbl w/ 10 gal foamer & 5 gal foam stabilizer, pump 50 sxs Class "C" cmt w/ 2% CaCl₂. Release 4", 10.46# csg wiper plug & displace cmt w/ 43 bbls 10ppb brine. Pump 20 sxs Class "C" Thixotropic to cap foam cmt. WOC 24 hrs
- ⑦ DO cmt to 3660' and press test to 1000 psi. Drill out cal-seal plug from 3660'-3670'. Reverse out pea gravel to 3800'. Set inj. pkr @ 3550'.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE

8-7-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

8-22-86

CONDITIONS OF APPROVAL, IF ANY:

Subject to
Like Approval

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) File

RECEIVED
AUG 25 1986
HOBBS OFFICE