

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-09079</u>	
5. Indicate Type of Lease <u>Fed.</u>	STATE ☐ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER <u>Injection</u>	7. Lease Name or Unit Agreement Name <u>South Eunice Unit</u>
2. Name of Operator <u>Coroco Inc.</u>	8. Well No. <u>#39</u>
3. Address of Operator <u>P.O. Box 400 - Hobbs, NM 88240</u>	9. Pool name or Wildcat <u>Eunice 7 Rms Area South</u>
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>28</u> Township <u>22S</u> Range <u>36E</u> NMPM <u>Sea</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: <u>Squeeze & pack, install liner</u> ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. Set pki. @ $\pm 475'$. Pump 75 sk Class "C" cmt down $8\frac{5}{8}" \times 5\frac{1}{2}"$ annulus. Pump 200 sk Class "C" cmt down $2\frac{7}{8}"$ working after closing annular valve. WOC. Perf. 3622-34, 38-40, 46-56, 3726-30, 3744-48 w/4 JSF (128 shots). Run $3\frac{1}{2}"$ fiberglass liner (3 jts). BOL @ 3610' Cement w/10 sk Class "C". Pump 250 sk Class "C" into thief zone. Squeeze to 1000-1500 psi surface. Drill out. Clean out. Acidize from 3622-3876 w/90 Bbls 15% HCl-NE FF. Had backwash w/180 bbls pk fluid pressure to 500 psi. Return to surf.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Zimmerman for TITLE Administrative Supervisor DATE 11-17-89
TYPE OR PRINT NAME W. W. Baker TELEPHONE NO. 397-5800

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

NOV 20 1989

NOV 15 1989

RECEIVED

NOV 20 1989

HOBBS