

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-025-09085</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>B. A. CHRISTMAS</b>
8. Well No. <b>1</b>
9. Pool name or Wildcat <b>JALMAT (TANSILL, YT, 7-RIV)</b>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator <b>MERIDIAN OIL INC</b>	
3. Address of Operator <b>P.O. Box 51810, Midland, TX 79710-1810</b>	
4. Well Location Unit Letter <b>L</b> : <b>1650</b> Feet From The <b>South</b> Line and <b>330</b> Feet From The <b>WEST</b> Line Section <b>28</b> Township <b>22-S</b> Range <b>36-E</b> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3508' GL</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MI RU, NU BOPE. POOH W/ 2-3/8" TUBING.

RIH W/ 2-3/8" TUBING, BIT AND SCRAPER. POOH.

RIH W/5 1/2" 17# CIBP ON TUBING AND SET @ 3086'. DISPLACE HOLE W/ 10 PPG GELLED BRINE MUD. MIX AND SPOT 25 SX CL C PLUG ON CIBP. POOH.

PERF 4 SQUEEZE HOLES @ 1740'-41'. RIH W/ 2-3/8" TUBING AND 5-1/2" CICR AND SET @ 1640'. SQUEEZE 50 SX CL C BELOW CICR. STING OUT OF PLUG AND CAP W/ 6 SX.

PU HOLE TO +/- 356' AND SPOT 36 SX CL C PLUG FROM 356' TO SURFACE. POOH. RD MO.

CUT CASING OFF 3' BELOW SURFACE. WELD STEEL PLATE AND P & A MONUMENT TO CASING STUB. RESTORE SURFACE AS DIRECTED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Williams TITLE Production Asst. DATE 11-17-93

TYPE OR PRINT NAME DONNA WILLIAMS TELEPHONE NO. 915/688-6943

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JAN 06 1994

CONDITIONS OF APPROVAL, IF ANY: