1 V MEXICO OIL CONSERVATION MMISSION

Santa Fe, New Mexico MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

NOTICE OF INTENTION TO TEST CASING SHUT-OFF		HUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL				XXX
NOTICE OF INTENTION TO CHANGE PLANS			NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING				
NOTICE OF INTENTION TO REPAIR WELL			NOTICE OF INTENTION TO PLUG WELL				
OTICE OF INTENTION							
					3.07.4	•	
		Wink,	Texas, Janu	lary 14,	, TA90	Date	
IL CONSERVATION CO	MMISSION		1100			Dute	
nta Fe, New Mexico.	Jimii 1551011,						
entlemen:				The) Texas	Compa	ny
ollowing is a notice of i			lescribed below at		1		1/4
Company or Operator League To				Well No. in South Eunice			
Sec. 28 T	22 5	Le 56 E	, N. M. P. M.,		Eunice		Fie
Lea	G.	ounty.					
	H'111.1. DH'	PAHSORPRO	OPOSED PLAN	OF WOR.	K		
otal depth 38: " Casing set o	.ow instruction 10'. at 3640'. 4000 gallo	ns in the Rule:	s and regulatio	rough t	COMMISSION		ker
otal depth 38: " Casing set o	.ow instruction 10'. at 3640'. 4000 gallo	ns in the Rule:	s and regulatio	rough t	COMMISSION		ker
otal depth 38:	.ow instruction 10'. at 3640'. 4000 gallo	ns in the Rule:	s and regulatio	rough t	COMMISSION		ker
otal depth 38: " Casing set (cidized with 4 et at 3663.	.ow instruction 10'. at 3640'. 4000 gallo	ns in the Rule:	s and regulatio	rough t	COMMISSION		ker
otal depth 38:	.ow instruction 10'. at 3640'. 4000 gallo	ns in the Rule:	XX acid the 4:05AM 1-2	rough t	ubing a		ker
otal depth 38: "Casing set a cidized with a et at 3663.	.ow instruction 10'. at 3640'. 4000 gallo	ns in the Rule:	XX acid the 4:05AM 1-2	rough t-36.	commission ubing a	nd pac	ker
otal depth 38: " Casing set a cidized with a cidize	.ow instruction 10'. at 3640'. 4000 gallo	ns Dowell acidizing	XX acid the 4:05AM 1-2	rough t-36.	ubing a	nd pac	ker
otal depth 38: " Casing set a cidized with a cidize	.ow instruction 10'. at 3640'. 4000 gallo	ns Dowell acidizing	XX acid the 4:05AM 1-2-	rough t-36.	OMPANY	nd pac	
otal depth 38:	.ow instruction 10'. at 3640'. 4000 gallo	ns Dowell acidizing	XX acid the 4:05AM 1-2- THE By Position Send	rough t-36.	OMPANY mpany or Ope Superin	nd pace	ıt.