

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instruction, reverse side)

Budget Bureau No. 1004-1
Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL
Nm 13125
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

OCT 5 10 55 AM '89

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	2. NAME OF OPERATOR Conoco Inc.	3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, NM 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit L 1980' FSL & 660' FWL	5. UNIT AGREEMENT NAME	6. FARM OR LEASE NAME Meyer A-29	7. WELL NO. #4	8. FIELD AND POOL OR WILDCAT Jalomat Yates Gas	9. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Sec. 29, T22S, R36E	10. COUNTY OR PARISH Lea	11. STATE NM
14. PERMIT NO. 30-025-09095	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3536' DF									

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☒
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Call Hobbs BLM Office AT 393-3612

MIRU. ND wellhead NU BOP. Set CIBP @ 3230'. Spot 25 AX cement on CIBP. POOH to 1808' & pump 10 AX cmt to spot plug across top of salt from 1808' to 1708'. Perf. 5 1/2" prod. csg. @ 357'. Establish circ up 10-3/4" x 5-1/2" annulus & pump 160 AX Cement to fill up annulus & set surface plug. ND BOP & cut off csg @ base of cellar. Fill csg string w/cmt to surface. Erect PTA marker. Restore location.

18. I hereby certify that the foregoing is true and correct

SIGNED W.W. Baker W. W. Baker TITLE Administrative Supervisor DATE 10-10-89

(This space for Federal or State office use)
Orig. Signed by Adam Salameh

APPROVED BY PETROLEUM ENGINEER TITLE 10-10-89 DATE

CONDITIONS OF APPROVAL, IF ANY:

MUD w/AMINUM 9 lbs/GAL. WT. Between PLUGS.

*See Instructions on Reverse Side