

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2657

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Continental Oil Company 3. Address of Operator Box 460, Hobbs, N. Mexico 88240 4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 22-S RANGE 36-E NMPM.	7. Unit Agreement Name 8. Farm or Lease Name State A-32 9. Well No. 2 10. Field and Pool, or Wildcat JALMAT YATES GAS
15. Elevation (Show whether DF, RT, GR, etc.) 3479' GR	12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input checked="" type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-25-77 Pull equipment. GIH w/sinker bar + tag bottom-fill at 3270'. CO fill to 3273'. Push junk in hole to 3376'. Found hole in casing between 387' + 418'.

3-26-77 Set BP at 3134' - spotted 35x sand on top of BP to 3095'

3-27-77 Squeeze off-cmt the leak in csg. w/2005x cement woc

3-28-77 Drilled out cmt. Circ out sand.

4-1-77 GIH w/ 4" Csg. gun + perf 2 JSPP @ 3233', 3242', 3252', 3267', 3278', 3306'

4-5-77 Pump 1000 gals. 15% HCL-NE. Flushed acid to perfs. Swab. Put on production

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. A. Butterfield TITLE ADMIN. SUPERV. DATE 5-17-77

APPROVED BY Larry Sexton TITLE Asst. L. Supv. DATE

CONDITIONS OF APPROVAL, IF ANY: NMOCC-4, File

REFILED

1977

OIL CONSERVATION COMM.
HABSB. H. M.