

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Atlantic Richfield Company 3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>35</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM. 5. Elevation (Show whether DP, RT, GR, etc.) 3475' GR 6. 7. Unit Agreement Name 8. Farm or Lease Name McDonald WN State 9. Well No. 1 7 10. Field and Pool, or Wildcat Jalmat Gas 11. 12. County Lea
--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up on 3/29/76. Killed well & installed BOP. WIH w/completion assy. RIH w/5½" CIBP, set BP @ 2900' on WL. Filled hole w/heavy gelled mud between all cmt plugs. Spotted 10 sx Cl C cmt on top of BP @ 2900' (35' cmt). Perf'd 5½" OD csg @ 1500', unable to pump thru @ 2000#. Perf'd 5½" csg @ 1400', unable to pump thru @ 2000#. Spotted 30 sx Cl C cmt 1300-1550'. Tagged TOC @ 1279' (271' cmt plug). Perforated 5½" csg @ 525', pmpd thru w/no PSI. WIH w/5½" cmt retr on 2-3/8" OD EUE tbg & set retr @ 483'. Cmtd 5½" X 8-5/8" annulus 0-525' w/95 sx Cl C Neat, circ 10 sx to surf. POH w/cmt stinger & 2-3/8" tbg. Spotted 10 sx cmt plug @ surface, installed regulation dry hole marker, cleaned & leveled location. P&A eff 4/1/76. Your office to be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Dist. Drlg. Supv.

DATE 4/5/76

APPROVED BY [Signature]

TITLE OIL & GAS INSPECTOR

DATE JUN

CONDITIONS OF APPROVAL, IF ANY: