

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

RECEIVED

OCT 3 1951

OIL CONSERVATION COMMISSION
HOBBBS OFFICE

Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting or results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL		Report of Shut-In Pressure Of High Pressure Gas Wells	X

October 2, 1951

Jal, New Mexico

Date

Place

Following is a report on the work done and the results obtained under the heading noted above at the

R. Olsen Oil Company King Well No. SE No. 1 in the
Company or Operator Lease
SE/4 of Sec. 1, T. 23 S., R. 36 E., N. M. P. M.
South Eunice Pool Lea County

The dates of this work were as follows:

Notice of intention to do the work ~~was~~ (was not) submitted on Form C-102 on _____, 19____
and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Shut-in pressure 24 hours, 1034 PSIG. Dead weight gauge used.

Witnessed by Fred Bernard
Name

El Paso Natural Gas Co. Gas En
Company Title

APPROVED:
OIL CONSERVATION COMMISSION

Ray Yarbrough
Name
Oil & Gas Inspector
Title

OCT 4 - 1951

Date

I hereby swear or affirm that the information is true and correct.

Name Lewey L. Linton

Position Geological Engineer

Representing R. Olsen Oil Company
Company or Operator

Address Drawer 121 Jal, New Mex