

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

P.O. Drawer DD, Artesia, NM 88210

DISTRICT II  
1000 Rio Brazos Rd., Aztec, NM 87410

|   |
|---|
| WELL API NO.<br>30-025-09236  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>  |
| 7. Lease Name or Unit Agreement Name<br>State A A/C 1   |
| 8. Well No.<br>43   |
| 9. Pool name or Wildcat<br>Jalmat Tansill Yates 7 Rvrs (Pro Gas)                                    |
| 10. Elevauon (Show whether DF, RKB, RT, GR, etc.)<br>   |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

|   |
|---|
| 1. Type of Well:<br>Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>   |
| 2. Name of Operator<br>Raptor Resources, Inc.   |
| 3. Address of Operator<br>901 Rio Grande, Austin, TX 78701  |
| 4. Well Location<br>Unit Letter <u>M</u> <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line<br>Section <u>3</u> Township <u>23S</u> Range <u>36E</u> NMPM <u>Lea</u> County |
| 10. Elevauon (Show whether DF, RKB, RT, GR, etc.)<br>   |

|   |  |
|---|--|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data |  |
| <b>NOTICE OF INTENTION TO:</b>  | <b>SUBSEQUENT REPORT OF:</b>   |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                                | REMEDIAL WORK <input type="checkbox"/>                               |
| PLUG AND ABANDON <input type="checkbox"/>                                     | ALTERING CASING <input type="checkbox"/>                             |
| TEMPORARILY ABANDON <input type="checkbox"/>                                  | COMMENCE DRILLING OPNS. <input type="checkbox"/>                     |
| CHANGE PLANS <input type="checkbox"/>   | PLUG AND ABANDONMENT <input type="checkbox"/>                        |
| PULL OR ALTER CASING <input type="checkbox"/>                                 | CASING TEST AND CEMENT JOB <input type="checkbox"/>                  |
| OTHER: <input type="checkbox"/>   | OTHER: Re-complete to Jalmat Gas <input checked="" type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/13/01 MIRU. POOH W/ Tbg, Rods & Pump. GIH W/ 7" csg scraoer ti 3685', POOH. GIH set 7" CIBP @ 3650', load hole W 2% KCl water & test plug to 500 #, held ok. Perf the Yates / 7 Rvrs W/ 1 SPF @ 3153', 3162', 3172', 3185', 3195', 3208', 3215', 3230', 3238', 3258', 3268', 3278', 3287', 3295', 3466', 3472', 3489', 3517', 3539', 3547', 3554', 3561', 3573', 3581', 3589' & 3595', for a total of 26 holes. GIH W/ tbg acidize perfs W/ 3700 gal 15 % HCl acid, POOH. GIH W. 7" ArrowSet II Pkr set @ 3058', load annulus W. 2% KCl water and test to 500#. Frac Yates/7 Rvrs perfs W/ 48,000 gal 40# Water Frac G foamed to 70 quality W/ 15,000# 20/40 and 175,000# 12/20 Brady sand. GIH release packer and POOH. GIH W/ 2 3/9" tbg tag sand @ 3395'. Clean out sand fill from 3395' to 3563', blew well dry, pull tbg above perfs. Lowered tbg tag sand fill @ 3527', clean aout to PBTD @ 3650', POOH. GIH W/ 2 3/8" tbg set @ 3438', 2" x 1 1/2" x 12' RWTC pump and rods.

3-23-01 RDMO. Well returned to production, as a Jalmat Gas well.

Test Dated 3-29-01: 0 / BO/D; 4 BW/D; 324 MCF

12. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Keathly TITLE R regulatory Agent for Raptor DATE 4/17/01  
TYPE OR PRINT NAME Bill R. Keathly, Regulatory Agent TELEPHONE NO. 915-697-1609

(this space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONITIONS OF APPROVAL, IF ANY:

