- <b>B</b> . I		1 1 1	<u> </u>			J	(Revised 7/ (Perm C
	╺┼╼╀╴	╶┼╼┽╾┾╸		NEW MEXI	CO OIL CON	SERVATION CO	<b>MMISSION</b>
+ +	╶┼╶┽╴	╺┼╌┽╌┽╸				New Mexico	
┼╌┼╴	╶┼╌┼╴	╶┼╌┼╶┼╴					•
┼╌┼╴		╺╀╸╉╸╋	-			RECORD	
┽╼╂╌	┽╼╇╌	╶┼╌┼╴┽╴			WELL	RECORD	20 C 2
┼╌┼╴	+-+-	╶┼╴┼╶┿╸					
╬╌╂╴	+	┽┥┥	Mail to I later than	District Office, Oil twenty days after	Conservation C completion of w	ommission, to which	Form C-101 was sent ons in Rules and Regulat
<u> </u>	REA 640		of the Co	mission. Submit in	QUINTUPLI	CATE. If Stat	• Land submit 6 Copie
LOCAT	TE WELL	CORRECTLY					
Albe	ert Gad	(Company or	(ator)		<u>S</u>	inclair State	
No	8	in NA	NW K of NW	14 of Sec 3	т	235 .	36E
Lan	gl <b>ie-</b>	Nattix		Bool	Lea	, 1	
<sub>is.</sub> 6	60*	feet fro	North		6601		Cou West
tion	3		If State Land the Oil			icet from	
ng Co	<u> </u>	·17-58		and Gas Lease No.		5_3_59	, 19
	acheed	G	ackle Drillin	, 19 Drillir 10 Company T	ig was Completed	d	, 19
of Drill	ing Conti	ractor	loy 2076 Hobb	c New Newdo		•••••••••••••••••••••••••••••••••••••••	
		U	<b>0</b> X 2010, <b>H</b> 055	S, NEW MEXIC	0		
tion abov	e sca leve	l at Top of Tu	bing Head	94	The ir	oformation given is	to be kept confidential u
from			and elevation to whic			_	
from			to		••••••	feet	
from			to		••••••	feet.	
from			to			feet.	
from from	WEI	oht ne	to to to to	CASING BECO	BD CUT AND	feet	
from from	WEIG FER 1	HT NE FOOT U	toto to to wor sed Amount	CASING BECO	ED CUT AND PULLED FROM	feet.	
from from size 5/8	WEI	HT NE FOOT U	toto to to WOR SED AMOUNT	CASING BECO	ED CUT AND PULLED FROM	feet	
from from size 5/8	WEIG PER 1 24	HT NE FOOT U	тоto to w or sed амоима 330 °	CASING BECO KIND OF SHOE Halliburt	ED CUT AND PULLED FROM	PERFORATIONS	
from from lize 5/8	WEIG PER 1 24	HT NE FOOT U	тоto to w or sed амоима 330 °	CASING BECO KIND OF SHOE Halliburt	ED CUT AND PULLED FROM	PERFORATIONS	
from from size 5/8	WEIG PER 1 24	HT NE FOOT U	тоtoto	CASING BECO KIND OF SHOE Halliburt	BD CUT AND PULLED FROM	PERFORATIONS	
from from size 5/8 1/2	WEIG PER 1 24	HIERE		CASING BECO KIND OF SHOE Halliburt " G AND CEMENTI	ED CUT AND PULLED FROM D D ING BECOBD	feet.	PURPOSE
from from size 5/8 1/2	WEI PER 1 24 14 SIZE OF CASING	WHERE SET	to           330 *           4038 *           MUDDING           NO. SACES           OF CEMENT	CASING BECO KIND OF SHOE Halliburto " G AND CEMENTI METHOD USED	ED CUT AND PULLED FROM D D ING BECOBD	feet.	PURPOSE
from from size 5/8 1/2  ile 1/4	WEIL PEE 1 24 14 14 size of Casing 3 5/8	HIERE		CASING BECO KIND OF SHOE Halliburt " G AND CEMENTI	ED CUT AND PULLED FROM D D ING BECOBD	feet.	PURPOSE
from from 5/8 1/2 5/8 1/2	WEIL PEE 1 24 14 14 size of Casing 3 5/8	WHERE SET 344	MUDDING NO. SACKS OF CEMENT 250	CASING BECO KIND OF SHOE Halliburto " G AND CEMENTI METHOD USED	ED CUT AND PULLED FROM D D ING BECOBD	feet.	PURPOSE
from from size 5/8 1/2 1/2 LE 1/4 {	WEIL PEE 1 24 14 14 size of Casing 3 5/8	WHERE SET 344	MUDDING NO. SACKS OF CEMENT 250	CASING BECO KIND OF SHOE Halliburto " G AND CEMENTI METHOD USED	ED CUT AND PULLED FROM D D ING BECOBD	feet.	PURPOSE
, from , from size 5/8 1/2 1/2	WEIL PEE 1 24 14 14 size of Casing 3 5/8	HT         NE           POOT         C           #         New           #         ''           WHERE         SET           344 '         4038 '	woe	CASING BECO KIND OF SHOE Halliburto " G AND CEMENTI METHOD USED 2 plug " PBODUCTION A	ED CUT AND PULLED FROM D I O I O I O I O I O I O I O I O I O I	MUD RAVITY	PURPOSE
from from size 5/8 1/2 1/2 1/2 1/4 5 7/8 5	WEI4 PER 1 24 14 812E OF CASING 3 5/8 5 1/2	3HT NE 7007 U * New * New * New * 17 * 19 * 19	woe         to           to         to           330 *         4038 *           4038 *         0           No. SACES         of CEMENT           250         1700           BECOBD OF         the Process used, N	CASING BECO KIND OF SHOE Halliburto " G AND CEMENT! METHOD USED 2 plug " PBODUCTION A Io. of Qts. or Gals	BD CUT AND PULLED FROM DB ING BECORD G ND STIMULAT used, interval	MUD RAVITY	PURPOSE
from from size 5/8 1/2 1/2 1/2 7/8 5	weil PER 1 24 14 size of CASING 3 5/8 5 1/2 te 3814	DHT         NE           **         New           *         New           *         *	MUDDING NO. SACES OF CEMENT 250 1700 BECOBD OF the Process used, N Ot s/foot. Tree	CASING RECOMEND OF SHOE Halliburto " GAND CEMENT BED 2 plug " PEODUCTION A To. of Qts. or Gals at w/250 gal	ED CUT AND PULLED FROM O  ING BECORD G ND STIMULAT A used, interval acid, 5000	feet.        feet.	PURPOSE

. Result of Production Stimulation

Test 45 bbl. oil 3 hrs. 0 water 20/64 choke. T.P. 175. C.P. 450 Depth Cleaned Out

**.** ..

## RECORD OF DRILL-STEM AND SPECIAL TESTS

	11	drill-stem or oth	er special was or devia	ation surveys were	e made, submit report of	n separ	ate sheet and attach he	reto -
				TOOLS				
Pot	and tools w	ere used from	0 feet to	T.D.	feet, and from	· • • • • • • • • • • • • • • • • • • •	feet to	fe <del>e</del> t.
Cab	le tools we	re used from	feet to		feet, and from		feet to	feet.
Ų40				PRODU				
Put	to Produc							
OII	WELL:	The production	during the first 24 hou	urs was	30 barrel	s of lic	98. quid of which	% was
							<b>2</b> % was	
		was oil;	% was er	nulsion;	% water; a	ina		seument. A.r.i.
		Gravity						
GA	S WELL:	The production	during the first 24 hou	Irs was	M.C.F. plus.		1	barrels of
0/1								
		liquid Hydroca	rbon. Shut in Pressure	lbs.				
Lei	ngth of Tir	me Shut in						
						GEOG	RAPHICAL SECTION	OF STATE):
	FLEMSE	MDIOATE DE	Southeastern New M				Northwestern Ne	
Т.	Anhy	1330	Т.	Devonian		т.	Ojo Alamo	
т.	Salt	1520	т.	Silurian		. Т.	Kirtland-Fruitland	<u>`</u>
в.	Salt	2830	Т.				Farmington	
Т.	Yates	3195	Т.				Pictured Cliffs	
т.	7 Rivers.	3522	Т.	McKee	3	. Т.	Menefee	
т.		3778	Т.	Ellenburger		. <b>T</b> .	Point Lookout	
Т.		•		Gr. Wash	••••	. <b>T.</b>	Mancos	•••••
т.		res		Granite		. Т.	Dakota	
Т.			Т.	•		. Т.	Morrison	
Т.						. Т.	Penn	•••••••••••••••••••••••••••••••••••••••
Т.						. т.		<u></u>
Т.	Abo		Т.			Т.		
Т.	Penn		т.			. Т.	·····	
Т.	Miss		<b>T</b> .			. Т.		
				FORMATIC	N RECORD			

## FORMATION RECORD

From	To	Thickness in Feet	Formation	From	То	Thickness in Feet	Formation
0 344 1520 2830 3195 3522 3778	344 1520 2830 3195 3522 3778 4038	344 1176 1310 365 327 256 260	Caliche, Sand, Red Bed Red Bed, Sand, Shale Salt, Anhydrite, Shale Dolomite, Sand Sand, Dolomite, Shale Lime, Sand, Shale Sand, Lime, Dolomite,				
	1000		Shale		4 *		
							1
			i t				-

ATTACH SEPARATE SHEET IF ADDITIONAL SPACE IS NEEDED .

. .

I hereby swear or affirm that the information given herewith is a complete and correct record of the well and all work done on it so far as can be determined from available records. May 12, 1958

Company or Operator Albert Gackle, Operator	Address Box 2076, Hobbs, New Mexico
Company or Operator Albert Gackle, Operator Original Signed By Name PALL S. JOHNSTON	Position or Title. Superintendent of Production
Name	