

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
NOTES: NEW MEXICO 88240

NOTICES AND REPORTS ON WELLS

1. NAME OF WELL  
2. LOCATION  
3. LEASE DESIGNATION AND DEPT. NO.

LC-030557(A)  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Farney A-5 SJS

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Talmat (T-Yts-7R)

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

Sec. 5, T-23-S, R-36-E

14. PERMIT NO.

30-025-09265

15. ELEVATIONS (Show whether DE, RT, OR, etc.)

12. COUNTY OR PARISH 13. STATE

Lea

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

☐  
☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

XX

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐  
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

10/7/87

RIH Knock out BP at 3600'. Set new BP at 3676

10/8/87

Perf 3651-3656 w/24. Acidized new perfs w/500 gal 15% NEFE.

10/9/87

Re-acidized and communicated to hole up the casing at 3448. Set retainer at 3640. Squeezed 100 sx into perfs. Perfed 3331-3457 w/39 shots. Acidized w/1500 gals. 15% NEFE. Swabbed load Waiting on gas connection for final completion

OK KE

RECEIVED  
MAR 7 8 25 AM '88

18. I hereby certify that the foregoing is true and correct

SIGNED

*Steve Burleson*

TITLE Vice-President

DATE 3/4/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

SJS