
OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REFORTS ON WELLS



Hobbs office

Title

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the wors specified is completed. It should be signed and sworn to be fore a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of	report by checking below:	
REPORT ON BEGINNING DRILLING OPERA-	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	REPORT ON PULLING OR OTHER ALTERING CASING	WISE
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL		
	Jal New Mexico March 31	1947
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO. Gentlemen:	FIECE	Date
Following is a report on the work done and the results of		
Western Gas Co. Company or Operator	King Well No.	in the
NW/4 SW/4 of Sec. 12	, t. <u>23</u> 5 , r. <u>36</u> E	, N. M. P. M.,
Cooper-Jal Field,	108	
The dates of this work were as follows:		
Notice of intention to do the work was (was not) submit		1947
	RK DONE AND RESULTS OBTAINED at 30° and comented with 2	20 ∞
	·	
sacks of coment circulated	back to surface. Tested i	for
which and Mant A W		
shut-off. Test 0, K.		
Witnessed by "Blondie" Guster		ol Pusher
Name	Company	Title
Subscribed and sworn before me this	I hereby swear or affirm that the inform is true and correct.	nation given above
day of, 19	Name X. 777° 77	oe f
	Position Production Foreman	
Notary Public	Representing Western Gas Com	pany
	Company or Operator Address Box 1384, Jal, New	Maxico
My commission expires	Address DUA 1704	
Remarks:	Roy ela	rhroll
APPROVED	7011 A G	as Inspector