

NEW MEXICO OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

OCCURRENCE OFFICE 000

MISCELLANEOUS NOTICES

1961 APR 7 AM 10:03

SUBMIT THIS NOTICE IN TRIPPLICATE TO THE DISTRICT OFFICE, OIL CONSERVATION COMMISSION, BEFORE THE WORK SPECIFIED IS TO BEGIN. A COPY WILL BE RETURNED TO THE SENDER ON WHICH WILL BE GIVEN THE APPROVAL, WITH ANY MODIFICATIONS CONSIDERED ADVISABLE, OR THE REJECTION BY THE COMMISSION OR AGENT, OF THE PLAN SUBMITTED. THE PLAN AS APPROVED SHOULD BE FOLLOWED, AND WORK SHOULD NOT BEGIN UNTIL APPROVAL IS OBTAINED. SEE ADDITIONAL INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION.

INDICATE NATURE OF NOTICE BY CHECKING BELOW

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO FENG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO PADDER		NOTICE OF INTENTION TO SHOOT (NITRO)	
NOTICE OF INTENTION TO GUN PERFORATE	X	NOTICE OF INTENTION (OTHER) Sand-Oil Frac	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICOHobbs, New Mexico
(PLACE)April 6, 1961
(DATE)

GENTLEMEN:

FOLLOWING IS A NOTICE OF INTENTION TO DO CERTAIN WORK AS DESCRIBED BELOW AT THE

Huble Oil & Refining Company N. M. State of _____ WELL NO. 5 IN G
(COMPANY OR OPERATOR)
SW 1/4 NE 1/4 OF SEC. 22, T. 23S, R. 26E, N.M.P.M., Lenlie Mattix (UNIT)
(ADDRESS DIVISION) POOL
Lee COUNTY.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Perforate 2-7/8-inch casing 3678-3700 feet.
Run tubing with retrievable bridge plug and hookwall packer or retrievable squeeze
tool; set bridge plug at 3745 feet; pull up and set packer at 3707'.
Pressure test for communications between perforated intervals. 1.9 cu ft.
If no communication, reset bridge plug at 3707 feet; pull tubing and frac perforations
3678-3700' with 15,000 gallons refined oil and 30,000 pounds sand.
Clean out, pull bridge plug, and place well back on production.

If communication exists between perforations, use same frac procedure as Step 5 with a
slug of naptha flakes in first part of frac.

APPROVED _____
EXCEPT AS FOLLOWS:

APR 7 1961

Huble Oil & Refining Company

COMPANY OR OPERATOR

ORIGINAL

SIGNED

ARVIN D. EADY

APPROVED _____
OIL CONSERVATION COMMISSION

COMMISSION AGENT

SEND COMMUNICATIONS REGARDING WELL TO:

BY _____
TITLE _____
Engineer District

Huble Oil & Refining Company

Box 2347, Hobbs, N. M.