

COPIES RECEIVED	
TRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No. <b>B-1506</b></p>
<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Disposal well</b></p> <p>2. Name of Operator <b>ALBERT GACKLE, OPERATOR</b></p> <p>3. Address of Operator <b>P. O. BOX 2038, HOBBS, NEW MEXICO 88240</b></p> <p>4. Location of Well UNIT LETTER <b>I</b>, <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>23</b> TOWNSHIP <b>23S</b> RANGE <b>36E</b> N.M.P.M.</p>	<p>7. Unit Agreement Name</p> <p>8. Name of Lease Name <b>Sinclair A State</b></p> <p>9. Well No. <b>5</b></p> <p>10. Field and Pool, or Wildcat <b>Langlie-Mattix</b></p>	
<p>15. Elevation (Show whether DF, RT, GR, etc.) <b>3369 DF</b></p>	<p>12. County <b>Lea</b></p>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set bridge plug at 3530'. Spot cement on top of bridge plug.

Perforate one hole each at 3520', 3512', 3507', 3498', 3496', 3480', 3468', 3462', 3456', 3446', 3420', 3384' and 3381'.

Acidize with 1000 gallons. Frac with brine water and 30000# sand.

Work to be commenced as soon as Commission grants permission.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Albert Gackle TITLE Operator DATE 9-19-1973

APPROVED BY John W. Runyan TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: