

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE O. C. C.

MISCELLANEOUS NOTICES

AUG 21 3 31 PM '64

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the school on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL	X	NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE	X	NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hobbs, New Mexico

August 21, 1964

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Gulf Oil Corporation Alice Paddeok Well No. 3 in P
(Company or Operator) (Unit)
SE 1/4, SE 1/4 of Sec. 1, T. 22S, R. 37E, NMPM, Blinbry Oil-Tubb Gas Pool
(40-acre Subdivision)
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

FB 6350. It is proposed to temporarily abandon the Blinbry Oil zone, acidize the Tubb Gas zone and produce as a single well in the Tubb Gas zone as per the attached procedures.

Approved....., 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By.....
Title.....

Gulf Oil Corporation

ORIGINAL SIGNED BY
Company or Operator

By..... C. D. BORLAND

Position..... Area Production Manager

Send Communications regarding well to:

Name..... Gulf Oil Corporation

Address..... Box 670, Hobbs, New Mexico

ALICE FANNOCK NO. 3 (Bl Oil - Tubb Gas)

Abandon Blinebry & Recondition Tubb Gas

Location: 660th FS&EL Sec. 1-22S-37E, Lea County, New Mexico.

Compl: 8-26-46 Tubb Gas

11-3-56 Blinebry

IP: "F" 30 bo + 1400 MCF Tubb

"F" 39 bo + 38 bw Blinebry

Cum. Prod: 1811 MMCF Tubb Gas thru 12-31-63

21,603 bo thru 12-31-63 Blinebry Oil

Present Status: "F" 0 Gas - Tubb

"F" 7 bo 3 bw Blinebry

SUGGESTED PROCEDURE

1. Kill well with no bloc.
2. Pull short and long strings of tubing.
3. Run Baker Model CB milling tool with DCs on tubing, mill out and retrieve Model "D" packer at 5980'.
4. If possible, fish tail pipe from Model "D" packer set at 6100'. Inspect the packing assembly to determine whether or not the Model "D" packer can be used for production purposes again.
 - a. Providing packer can be used, run in hole with tubing open ended and wash down below bottom of Tubb Gas perfs at 6250'. POH & run tbg w/receptacle seal assembly and tail pipe.
 - b. If packer cannot be used again, mill out and retrieve Model "D" packer at 6100' with Baker Model CC or CB milling tool, type depending on whether tail pipe is recovered. Then run in hole with tubing open ended and wash down below bottom of Tubb Gas perforations at 6250'. POH and run in hole with retrievable packer to be used for acidizing as specified in Step No. 5.
5. After determining the usability of the Model "D" packer and washing down to the bottom of the Tubb perforations, acidize the Tubb Gas zone as follows: Spot 500 gals 15% NEA across perfs and let soak on perforations. Then squeeze remaining acid into formation.
6. Swab and test.
7. Run one (1) joint 2-3/8" tubing on short string side (Blinebry) and shut in.
8. Place Tubb Gas zone on production and run packer leakage test as required.

ALICE PADDOCK NO. 3 (Bl Oil - Tube Well)

TH = 9°

CH = 7°

Gr. Elev - 3358°

