

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR NOTICES TO OWNERS TO OPEN OR CLOSE A WELL OR TO A DIFFERENT RESERVOIR. USE THIS FORM FOR REPORTS ON WELLS OPERATED BY THE COMMISSION.)		5a. Indicate Type of Lease State ☐ Fee ☐ 5. State Oil & Gas Lease No.
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER 2. Name of Operator 3. Address of Operator 4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> AMPH.		7. Unit Agreement Name 8. Name of Lease Name <u>Annie Christmas</u> 9. Well No. <u>1</u> 10. Field and Pool, or Valued <u>Drinkard-Wantz</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3348.7 GR</u>		12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER <u>Downhole Comingle Drinkard and Wantz Granite Wash.</u> ☒	PLUG AND ABANDON ☐ CHANGE PLANS ☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPER. ☐ CASING TEST AND CEMENT JOB ☐ OTHER ☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 7402, PBDT 7369, Wantz Perfs 7217-7296, Drinkard Perfs 6291-6845.

1. MIRU. Unseat pump in lower tbq. Pump 50 bbl hot oil down lower tbq, wait 1 hr. POH w/rc Install Hydril BOP.
2. RIH w/taper tap on sucker rods & screw into 11/16" hole in mechanical hold down @ 4921. F & POH and lay down rods.
3. Otis set latch in standing valve in "X" nipple at 7180'.
4. Kill Drinkard w/dead lease oil thru upper tbq; Un-jay upper tbq from "RDH" pkr @ 4849 & PO laying down.
5. Release "RDH" pkr w/straight pull on lower tbq, pull out of overshot @ 7181' & retrieve du equipment. (Note: 1" UT Retrieve w/LT.)
6. Install 7" x 2 1/2" single wellhead & run OS W/O lugs; 1 jt. 2-3/8; Otis "C". Nipple, 900 2-3/8", 5" TAC, 3950' 2", 4.7#, J-55, & 2000' 2 1/2", 6.5# J-55.
7. Run 1 1/2" insert pump on 86 rod taper (74-1", 74-7/8", 127-3/4").
8. RD RR. Align pumping unit. POP @ 8 x 74 x 1 1/2. Test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Casson Muntzel TITLE Production Staff Associate DATE 4-18-79

Orig. Signed by
Jerry Sexton

APPROVED BY Dist 1, Supv. TITLE _____ DATE MAY 25 1979

CONDITIONS OF APPROVAL, IF ANY

RECEIVED

APR 2 0 1979

OIL CONSERVATION COMM.
HUDSB. N. M.