

**TRIPPLICATE**

# OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

**RECEIVED**  
JUN 12 1947  
**HOBB'S OFFICE**

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	X	REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL		REPORT ON SQUEEZING OFF PERFORATION	X

June 10, 1947

Hobbs, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,  
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the  
**The Ohio Oil Company** **Walter Lynch** Well No. **5** in the

Company or Operator **NE/4, NW/4** of Sec. **1**, T. **22-S**, R. **37-E**, N. M. P. M.,  
**Drinkard** Field, **Lea** County.

The dates of this work were as follows:

Notice of intention to do the work was (~~received~~) submitted on Form C-102 on **June 6,** 1947  
and approval of the proposed plan was (~~received~~) obtained. (Cross out incorrect words.)

### DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Total depth 6575' Lime. P. B. 5343'. After squeezing off perforation from 5173' to 5200' W/85 sks cement, then perforated from 5230' to 5213' W/102 - 1/2" shots, set tubing @ 5335'. Set packer @ 5203', acidized W/1000 gal. 20% acid, swabbed load oil and acid water, then swabbed 40 bbls. salt water.

Witnessed by **J. B. Reese** **The Ohio Oil Company** **Foreman**  
Name Company Title

Subscribed and sworn before me this

I hereby swear or affirm that the information given above is true and correct.

**10** day of **June**, 19**47**

Name **P. B. Stewart**

Position **Superintendent**

Representing **The Ohio Oil Company**  
Company or Operator

Notary Public

My commission expires

Address **Box 1607- Hobbs, New Mexico**

Remarks:

**APPROVED**

Date **JUN 12 1947**

**Roy. W. H. H. H.**  
**Oil & Gas Inspector**

Title