

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
BY	
S.G.S.	
AND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

69952

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR REPORT OF WORK (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Exxon Corporation

Address of Operator

Box 1600, Midland, Texas 79702

Location of Well

UNIT LETTER P 660 FEET FROM THE East LINE AND 660 FEET FROM

THE South LINE, SECTION 2 TOWNSHIP 22-S RANGE 37-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3359 RDB

5a. Indicate Type of Lease

State ☒

Fee ☐

5. State Oil & Gas Lease No.

B-934

7. Unit Agreement Name

8. Farm or Lease Name

New Mexico "S" State

9. Well No.

2

10. Field and Pool, or Wildcat

Eunice-San Andres

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
WELL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOG ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spot 100' Cmt plug above San Andres (20 Sx) from 3800' to 3700' and above Queen (20 Sx) from 3300-3200'.
- Determine free point of 5 1/2" csg. - cut & pull.
- Spot 100' (50 Sx plug across 5 1/2" cut.
- Determine free point of 7 5/8" csg. *none @*
If free point is above 1200'
A. spot 200' (60 Sx) plug inside 7 5/8" csg. from 1200' to 1000' above salt.
B. cut and pull 7 5/8" csg. if free point is at or below the surface csg seat at 334'.
- Set a 100' Class "C" cmt from 385-285' across (10 3/4") csg. seat and below the ogallala. 30 sx. if in 7 5/8 - 55 sx if in 10 3/4".
- Spot 10 sx. plug at surface.
- Install dry hole marker as required by NMOCC.

ALL OPERATIONS FOR THE CLOSING OF THIS WELL MUST BE APPROVED BY THE COMMISSION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton

TITLE WELL HEAD

DATE 4-10-79

Orig. Signed by

Jerry Sexton

District 1, Super

TITLE

DATE APR 26 1979

CONDITIONS OF APPROVAL, IF ANY: