

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002509961
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-934
7. Lease Name or Unit Agreement Name NEW MEXICO S STATE
8. Well No. 12
9. Pool name or Wildcat BLINEBRY OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORMC-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator EXXON CORPORATION	
3. Address of Operator ATTN: REGULATORY AFFAIRS P. O. BOX 4358 HOUSTON, TX 77210	
4. Well Location Unit Letter A : 660 Feet From The NORTH Line and 760 Feet From The EAST Line Section 2 Township 22S Range 37 NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3370' DF	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:


REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **SQZ BLINEBRY/ADD PERES IN TUBB** ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PAGE 2

12/28/98 CONTINUE DRLG AT 5890 TO 6160, TEST SQZE TO 1000 PSI. LOST PRESS. @ A STEADY RATE OF APPROX 50 PSI PER MIN.
12/29/98 SET PKR @ 6120', PRESS TO 1000 PSI BELOW PKR., HELD OK, PULLED UP, SET PKR @ 5880', PRESS TO 1000 PSI BELOW PKR, HELD OK PULLED UP TO 5817', PRESS TO 1000 PSI BELOW PKR, LOST 120 PSI IN 8 MIN, PRESS TO 1000 PSI ABOVE PKR, LOST 200 PSI IN 2 MIN., RELEASED PKR, POOH
12/30/98 PERF THE TUBB FORMATION FROM 5988-6149', (RHSC, 4' GUN 1 SPF)
12/31/98 ACIDIZED TUBB (5988-6132') W/3000 GALS 15% HCL W/4000 MAX PSI. FRAC'D (5988-6149) W/61000 GALS FLUID, 123000 LBS SAND

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE **Sr Staff Office Assistant** DATE **06/11/99**
TYPE OR PRINT NAME **Patti Sandoval** (713) 431-1212 TELEPHONE NO.

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR TITLE _____ DATE **JUL 23 1999**

CONDITIONS OF APPROVAL, IF ANY:

3
2