

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fed <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Exxon Corporation		8. Farm or Lease Name Paddock Unit
3. Address of Operator P. O. Box 1600, Midland, TX 79702		9. Well No. 40
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> MAPS.		10. Field and Pool, or Wildcat Paddock
11. Elevation (Show whether DF, RT, GR, etc.) 3390' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled rods and tubing.
2. Set CIBP at 4950' w/10 sx plug on top.
3. Set 20 sx plug at 3800' and 20 sx plug at 3300', top of plug 3160'.
4. Cut 5 1/2" csg at 3150', and pulled
5. Spot 30 sx plug at 3160', top of plug 3070. Spot 35 sx plug at 2850', top of plug 2760'.
6. Spot 70 sx plug at 1200'.
7. Cut 8 5/8" csg at 570', and pulled.
8. Spot 75 sx plug at 620', top of plug at 484'.
9. Spot 75 sx plug at 390', top of plug at 332'. Spot 40 sx plug at 332', 10 sx plug at surface.
10. Installed dry hole marker as required by NMOCC.
FRW 11-26-79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. J. [Signature]TITLE Unit HeadDATE 12-5-79APPROVED BY [Signature] (MAP)TITLE OIL & GAS INSPECTORDATE AUG 10 1983

CONDITIONS OF APPROVAL, IF ANY: