

OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO 88240

June 16, 1969

Cities Service Oil Co.
Box 69
Hobbs, New Mexico

Gentlemen:

This office is in receipt of a Packer Leakage Test and Forms C-103 covering your Brunson "C" Well No. 4 located in Unit J of Section 3, T-22-S, R-37-E. As you know, this well had been shut in because a Packer Leakage Test submitted on April 26, 1968 indicated communication in the well bore.

On your recent Packer Leakage Test which you submitted June 10, 1969, you state that there is no leak indicated during the test. However, while flowing the Drinkard zone there was a 50 pound pressure decline on the Blinebry zone, and while flowing the Blinebry zone there was a 275 pound decline on the Drinkard zone. This, to me, indicates that there is still communication between zones in this well, and it is still necessary that the communication be repaired immediately.

Please commence this work immediately so that this office will not have to take more drastic measures.

Yours very truly,

OIL CONSERVATION COMMISSION

Joe D. Ramey
Supervisor, District 1

JDR/mc

REPORT NEW MEXICO 88247
DE DECLASSIFICATION COMMISSION