

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name BRUNSON "C"
8. Well No. 6
9. Pool name or Wildcat DRINKARD-TUBB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> TUBB <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator JOHN H. HENDRIX CORPORATION
3. Address of Operator P.O. BOX 3040, MIDLAND, TX 79702	4. Well Location Unit Letter I : 2080 Feet From The SOUTH Line and 560 Feet From The EAST Line Section 3 Township 22-S Range 37 NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-11-96 CUT OVER MODEL "D" PKR. @ 6400' & PUSHED TO 6520'.
4-12-96 SET CEMENT RETAINER @ 5800' & SQUEEZED DRINKARD OH 6448-6550' & TUBB
PERFS 5840-6160' W/200 SXS CLASS "C" CEMENT.
4-15-96 DRILL OUT CEMENT F/5800-6410'.
4-16-96 PERF TUBB F/5939-6161'.
4-17-96 ACIDIZED PERFS 5939-6161' W/3000 GALS.
4-22-96 FRAC TUBB.
4-23-96 THRU 5-1-96 TESTING WELL.
5-02-96 RUN RODS & PUT ON PUMP.

DRINKARD IS NOW ABANDONED
TUBB COMPLETION ONLY

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ronnie H. Westbrook TITLE VICE-PRESIDENT DATE 5-21-96
TYPE OR PRINT NAME RONNIE H. WESTBROOK TELEPHONE NO. 915-684-6631

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

MAY 23 1996

2D Drinkard