

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

L CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER Dual		7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Co.		8. Farm or Lease Name Eva Owens
3. Address of Operator P. O. Box 1861 - Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER D 660 FEET FROM THE N LINE AND 660 FEET FROM THE W LINE, SECTION 3 TOWNSHIP 22 RANGE 37 NMPM.		10. Field and Pool, or Wildcat Drinkard/Tubb Gas
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Cellar Inspection

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Dug out cellars to expose csg. heads.

Surface csg 2" line (H.P.) to surface w/valve.

Int. csg 2" line (H.P.) to surface w/valve.

Int. csg 2" line (H.P.) to surface w/valve.

Prod. csg valve @ surface Tubb flow.

All lines to surface marked for identification.

Inspected 3-28-83 R. M. Castleberry "O. C. D."

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elmer Teel by Dist. Am. Insp. TITLE Foreman DATE 4-5-83

APPROVED BY Ronald M. Castleberry TITLE OIL & GAS INSPECTOR DATE APR 12 1983

CONDITIONS OF APPROVAL, IF ANY: