

NEW MEXICO OIL CONSERVATION COMMISSION

Supersedes Old
C-102 and C-103
Effective 1-1-65

FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name H. Corrigan
3. Address of Operator Drawer "D", Monument New Mexico 88265	9. Well No. 6
4. Location of Well UNIT LETTER <u>B</u> <u>2051'</u> FEET FROM THE <u>East</u> LINE AND <u>721</u> FEET FROM THE <u>North</u> LINE, SECTION <u>4</u> TOWNSHIP <u>22=S</u> RANGE <u>37=E</u> NMPM.	10. Field and Pool, or Wildcat Wantz Abo
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to set cast iron bridge plug at approx. 5900' with cement on top. Abandon Wantz Abo zone. Perforate Blinebry zone selectively from approx. 5583' to 5800'. Frac and acidize as necessary. Run production equipment and complete as a pumping oil well in Blinebry zone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>MD Blush</u>	TITLE <u>Supver ., Admin. Services</u>	DATE <u>8-18-75</u>
APPROVED BY <u>John Runyan</u> Orig. Signed by Geologist	TITLE <u>Geologist</u>	DATE <u>8-18-75</u>
CONDITIONS OF APPROVAL, IF ANY		