Submit 3 Copies to Appropriate District Office

State of New Mexico Energy **inerals and Natural Resources Department

Form C-103 Revised 1-1-89

PI	NO.	 	

P.O. Box 1980, Hobbs, NM 88240		ON DIVISION	WELL API NO.	
	2040 Pacheco St. Santa Fe, NM		30 - 025 - 10020	
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Leese STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.	
CUNIDDY NOTICES AND DE	DODTE ON W	EI I C		
SUNDRY NOTICES AND RE (DO NOT USE THIS FORM FOR PROPOSALS TO DE	RILL OR TO DEEPE	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "AF (FORM C-101) FOR SUCH		PERMIT"		
l. Type of Well:	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Clifton	
OI GYZ	OTHER			
Name of Operator BEC Corporation			8. Well No.	
3 Address of Operator	,	TI TOO	9. Pool name or Wildcat	
P.O. Box 1392 Midland	, Texas	797CZ	Penrose Skelly Gr	reyburg
4. Well Location Unit Letter M.: 660 Feet From T	South	1 in and	060 	est
Unit Detter : Pea From I			red From the	Line
Section 4 Township		Range 37E	NMPM Lea	County
//////////////////////////////////////	lev alica (Show wheth 34,31 GR	er DF, RKB, RT, GR, etc.)	<i>\\\\\\\</i>	
1. Check Appropriate		Nature of Notice, R	enort or Other Data	
NOTICE OF INTENTION T		•	SEQUENT REPORT (OF:
	_	1	[TV]	·
ERFORM REMEDIAL WORK L. PLUG AND	D ABANDON	REMEDIAL WORK	ALTERING O	ASING
EMPORARILY ABANDON CHANGE	PLANS	COMMENCE DRILLIN	G OPNS. PLUG AND A	ABANDONMENT L
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB	
OTHER:		OTHER:		
	e all pertinent desails.	and give pertinent dates, incl	iding estimated date of starting any p	roposed
Test Casing. Replace Run Production String Moved in Fumping Unit.	e Top Sub. Bottom (o) & Test Wel	e Puma & Rods		ropased
Test Casing. Replace Run Production String Moved in Fumping Unit. Produced 1 Bbl. Cil, I hereby certify that the information above is true and complete to the SIGNATURE TYPE OR FRINT NAME 0.T. Maxwell OHIGINAL SIGNED BY	E Top Sub. Bottom iol & Test Wel 1 Bbl. Wat	e Punc & Rods 1. ter & 20 MCF Gas/ mus Production 915	Sert. Date	Ú−5−98 E NO.
Test Casing. Replace Run Production String Moved in Fumping Unit. Produced 1 Bbl. Cil, Thereby certify that the information above is true and complete to the SIONATURE TYPE OR FRINT NAME U.T. Maxwell	E Top Sub. Bottom i ol & Test Wel 1 Bbl. Wat best of my knowledge. CHRIS WILLIAM PERVISOR	e Punc & Rods 1. ter & 20 MCF Gas/ mus Production 915	Sert. Date	ú−5−98